



# City of Albuquerque Stormwater Construction Site Inspection Report

## General Information

Project Name:	Maverik		
Location:	650 Juan Tabo		
Site Contact Name & Agency	Jason - Insight Const <a href="mailto:jason@insisghtnm.com">jason@insisghtnm.com</a>	ESC File No.	K22E059
		NPDES Id. No.	NMR10022L
Inspection Date:	05/14/20	Start/End Time:	0820/0825hrs
CoA Stormwater Inspector:	Timothy E. Sims		
Construction Phase:	vertical		
Type of Inspection:	<input checked="" type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25" <input type="checkbox"/> 311/Complaint <input checked="" type="checkbox"/> Follow Up

Weather at time of inspection?	Clear	Temperature: ~	66*
Estimated date of last storm 0.25" or greater	4/13/2020		

Item Number	Deficiency/ Corrective Action		
	no issues observed with this inspection		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date: 5/11/2020

Notes:	This project requires SWPPP self-inspection reporting until the work order is complete on Juan Tabo.

City of Albuquerque Stormwater Inspector Signature and date:  
Contact information: Timothy E. Sims - (505) 803-6155  
[tsims@cabq.gov](mailto:tsims@cabq.gov) 05/14/20