



City of Albuquerque  
Stormwater Construction Site  
Inspection Report

General Information

Project Name and Location	Nuestras Valures School 6300 Gonzales Rd SW		
Site Contact Name & Agency		ESC File No.	L10E007
Date of Inspection	8-15-17	Start/End Time	9:40/
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality		
Describe Present Phase of Construction	Stabilized		

Type of Inspection:

☒ Regular    • During storm event    • Post-storm event (> 0.5 inch)    • 311 / Complaint Response    • Follow-Up

Weather Information

Weather at time of this inspection?

Temperature: ~ 75 F°

☒ Clear    • Cloudy    • Rain    • Sleet    • Fog    • Snowing    • Windy

Has there been a storm event since the site was Permitted?    • Yes    • No

Amount:    • < 1/4"    • 1/4" to 3/4"    • > 3/4"    • Snow \_\_\_\_\_"

Erosion & Sediment Control Inspection

Entrance / Track-Out	Stabilized  pads, gravel
Sediment Controls / Silt Fence, Inlet Protection, Wattles, etc.	
Erosion Controls	
Housekeeping/Pollutant Controls	
Debris/Pollutants/Sediment in MS4	
Notes	

Is site being maintained in compliance with the Drainage Ordinance? (Yes) No

Curtis Cherne 8-15-17  
Signature Date