City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	L10E030	Project Name:	Sage Park Subdivision
NPDES Id. No.	NMR1006LS	Location:	6601 Sage Rd SW

11/19/2025	Owner	Contractor
Operator	Stillbrooke Homes	
Contact name & title	Chris Kelsey	
e-mail	ckelsey@stillbrooke.com	
Contact Phone #	505-585-1800	

COA Inspector	**Chancellor English**	Start/End Time:	10:30am
Construction Phase:	Grading, WO		

Type of Inspection:	Regular	Storm Event	Post Storm Event >0.25"	311/Complaint	Follow Up

Weather at time of inspection?	Cloudy	Temperature: ~	55
Estimated date of last storm 0.25" or greater		10/14/2025	

Item Number	Deficiency/ Corrective Action			
1	None			
2.1	Discharge off site? (Y/N)	no		
4	Self Inspection Reports	Yes	Latest report Date:	11/4/2025

Notes:
The SWPPP is located in the box mounted on the back of the Stillbrooke sign next to posting at the southeast entrance of the subdivision.

City of Albuquerque Stormwater Inspector Signature and date: 11/18/2025

Contact information: Chancellor English (505) 924-3325

cenglish@cabq.gov

Chancellor English