



General Permit SWPPP Inspection

Site Name:	<u>Raising Cane's - Gibson</u> <u>1400 Gibson Blvd SE, Albuquerque, NM 87106</u>	Inspector:	Marcos Valadez
Permit #:		Inspection Frequency:	Bi-weekly -
Date of Visit:	Jan 11, 2024, 8:29:15 AM	Last Rain Event --	Last Precipitation -- 48h Forecast 70% Chance of Rain

Inspection Form Instructions

Review each question for this inspection carefully, then answer YES, NO, or N/A (not applicable). If any of the items below are out of compliance, press the "Add Action Item" button above to add a corrective action.

General Information

Inspector's Qualifications

Trained and work experience - see inspector qualification page in section 2 of the SWPPP.

Type of Inspection:

- ☒ **Regular** ☐ During storm event
☐ Post-storm event

Weather Information

Last Storm Event Information

For information on the last storm event, see the weather event information at the end of this inspection.

Weather at time of this inspection?

- ☐ Clear ☐ Cloudy ☐ Rain ☐ Sleet
☐ Snowing ☐ High Winds ☒ **Partly Cloudy**

Have any discharges occurred since the last inspection?

- ☐ Yes ☒ No

If yes, what did the water look like at the time of the discharge?

Are there any discharges at the time of this inspection?

- ☐ Yes ☒ No

If yes, what did the water look like at the time of the discharge?

Is a rain gauge installed on site?

- ☐ Yes ☒ No

If yes, where is it located?

Representative weather site is used to measure precipitation.

Has the Rain Event Page been filled out?

- ☒ Yes ☐ No

Are there SDS sheets on site?

- ☒ Yes ☐ No

If yes, where are they located?

On site job trailer

If construction ceases on the site for more than 14 days, the site must be stabilized until construction resumes.

Date Construction Stopped

Date Construction Resumed

Measures Taken to Stabilize the Site:

Construction Phasing



General Permit SWPPP Inspection

Site Name:	<u>Raising Cane's - Gibson</u> <u>1400 Gibson Blvd SE, Albuquerque, NM 87106</u>	Inspector:	Marcos Valadez
Permit #:		Inspection Frequency:	Bi-weekly -
Date of Visit:	Jan 11, 2024, 8:29:15 AM	Last Rain Event --	Last Precipitation -- 48h Forecast 70% Chance of Rain

Verify what stage of construction the project is in, and record dates when activities started and were completed.

Installed BMPs

Completed

Started:

Completed:

1/2024

Site Clearing and Grading

Started

Started:

Completed:

Installing Utilities

Started

Started:

Completed:

Building Structure

Started

Started:

Completed:

Paving and Walks

Started:

Completed:

Final Grading/Stabilize Site

Started:

Completed:

Other

Started:

Site-specific BMPs

The corrective actions initiated and date completed are in the Corrective Action Log

List of BMPs Installed:

Stabilized construction entrance, silt fence, mulch socks, roll off, concrete washout, portable toilet

Are all of the above controls installed?

Yes

No

Do any of the above controls need maintenance?

Yes

No

If any of the controls have not been installed or require maintenance, please list the control and explain.

The track out needs to be refreshed. (add more rock) They contacted inspections plus to do it and also sweep the street at the entrance/ exit of the site for off site tracking.



General Permit SWPPP Inspection

Site Name:	<u>Raising Cane's - Gibson</u> <u>1400 Gibson Blvd SE, Albuquerque, NM 87106</u>	Inspector:	Marcos Valadez
Permit #:		Inspection Frequency:	Bi-weekly -
Date of Visit:	Jan 11, 2024, 8:29:15 AM	Last Rain Event --	Last Precipitation -- 48h Forecast 70% Chance of Rain

Are the BMPs shown on the map?

Yes

No

Were there any changes to the SWPPP?

Has the SWPPP been updated?

Were the changes to the SWPPP implemented within 7 days?

List any new BMPs needed:

No new BMP's needed at this time.

Notes:

Vertical construction in progress. Utilities continue to be installed. As soon as TLC finishes installing wet utilities on the west side, the silt fence will need to be reinstalled.

Oversight Issues

A list of corrective actions will be supplied with this inspection.

1. Are all slopes and disturbed areas not actively being worked properly stabilized?

Implemented?

Yes

No

N/A

Maintenance Required?

Yes

No

N/A

2. Are natural resources (e.g., streams, Arroyos, mature trees, etc.) protected with barriers or similar BMPs?

Implemented?

Yes

No

N/A

Maintenance Required?

Yes

No

N/A

3. Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?

Implemented?

Yes

No

N/A

Maintenance Required?

Yes

No

N/A

4. Are discharge points and receiving waters free of any sediment deposits?

Implemented?

Yes

No

N/A

Maintenance Required?

Yes

No

N/A

5. Are storm drain inlets properly protected?

Implemented?

Yes

No

N/A

Maintenance Required?

Yes

No

N/A

6. Is the construction exit preventing sediment from being tracked into the street?



General Permit SWPPP Inspection

Site Name:	<u>Raising Cane's - Gibson</u> <u>1400 Gibson Blvd SE, Albuquerque, NM 87106</u>	Inspector:	Marcos Valadez
Permit #:		Inspection Frequency:	Bi-weekly -
Date of Visit:	Jan 11, 2024, 8:29:15 AM	Last Rain Event --	Last Precipitation -- 48h Forecast 70% Chance of Rain

Implemented?

☒ Yes ☐ No ☐ N/A

Maintenance Required?

☐ Yes ☐ No ☐ N/A

7. Is trash/litter from work areas collected and placed in dumpsters?

Implemented?

☒ Yes ☐ No ☐ N/A

Maintenance Required?

☐ Yes ☒ No ☐ N/A

8. Are washout facilities (e.g., paint, stucco, concrete) available, clearly marked, and maintained?

Implemented?

☒ Yes ☐ No ☐ N/A

Maintenance Required?

☐ Yes ☒ No ☐ N/A

9. Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material?

Implemented?

☐ Yes ☐ No ☒ N/A

Maintenance Required

☐ Yes ☐ No ☒ N/A

10. Are materials that are potential storm water contaminants stored inside or under cover?

Implemented?

☒ Yes ☐ No ☐ N/A

Maintenance Required?

☐ Yes ☒ No ☐ N/A

11. Are non-storm water discharges (e.g., wash water, dewatering) properly controlled?

Implemented?

☐ Yes ☐ No ☒ N/A

Maintenance Required?

☐ Yes ☐ No ☒ N/A

12. Has the Site map been updated to reflect current conditions?

Implemented?

☒ Yes ☐ No ☐ N/A

Maintenance Required?

☐ Yes ☒ No ☐ N/A

13. Is the NOI posted?

Implemented?

☒ Yes ☐ No ☐ N/A

Maintenance Required?

☐ Yes ☒ No ☐ N/A



INSPECTIONS PLUS

General Permit SWPPP Inspection

Site Name:	<u>Raising Cane's - Gibson</u> <u>1400 Gibson Blvd SE, Albuquerque, NM 87106</u>	Inspector:	Marcos Valadez
Permit #:		Inspection Frequency:	Bi-weekly -
Date of Visit:	Jan 11, 2024, 8:29:15 AM	Last Rain Event --	Last Precipitation -- 48h Forecast 70% Chance of Rain

14. Were previous corrections made within 7 days of last inspection or before the next storm event?

Implemented?

Yes

No

N/A

Maintenance Required?

Yes

No

N/A

Walk through facility and look for signs of pollution including paint, solvents, chemicals, solid waste, oil, and fuel.

Are there any signs of hazardous materials being exposed to storm water runoff?

Yes

No

Have there been any reportable quantities releases of hazardous materials?

Yes

No

Additional Notes

Site Superintendent - Shane. 512 - 630-9651
Inspections Plus is preparing the certification and delegation letters to be signed and put in the swppp book.

Certification & Signatures

Certification Statement:

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Electronic Signature

X **Marcos Valadez**

Date

January 11, 2024 at 9:52:48 AM MST

Title

Inspector

Electronic Signature

X **Robert F. Montgomery**

Date

January 26, 2024

Title

Sr. Property Development Director



INSPECTIONS PLUS

General Permit SWPPP Inspection			
Site Name:	<u>Raising Cane's - Gibson</u> <u>1400 Gibson Blvd SE, Albuquerque, NM 87106</u>	Inspector:	Marcos Valadez
Permit #:		Inspection Frequency:	Bi-weekly -
Date of Visit:	Jan 11, 2024, 8:29:15 AM	Last Rain Event --	Last Precipitation -- 48h Forecast 70% Chance of Rain

Photos





General Permit SWPPP Inspection

Site Name:	<u>Raising Cane's - Gibson</u> <u>1400 Gibson Blvd SE, Albuquerque, NM 87106</u>	Inspector:	Marcos Valadez
Permit #:		Inspection Frequency:	Bi-weekly -
Date of Visit:	Jan 11, 2024, 8:29:15 AM	Last Rain Event --	Last Precipitation -- 48h Forecast 70% Chance of Rain

Weather History



Precipitation
Recorded



No
Precipitation



Missed or data
unavailable

October

January

10 th

0

11 th

0

All precipitation totals are obtained from the National Oceanic and Atmospheric Administration (NOAA). Precipitation readings are based on the latitude and longitude for each site as entered into complianceGO. Occasionally NOAA fails to return/record data. Days where this occurs are so indicated.



INSPECTIONS PLUS

General Permit SWPPP Inspection

Site Name:	<u>Raising Cane's - Gibson</u> <u>1400 Gibson Blvd SE, Albuquerque, NM 87106</u>	Inspector:	Marcos Valadez
Permit #:		Inspection Frequency:	Bi-weekly -
Date of Visit:	Jan 11, 2024, 8:29:15 AM	Last Rain Event --	Last Precipitation -- 48h Forecast 70% Chance of Rain

There Are No Action Items