



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	L20E075	Project Name:	JB Henderson New Fabrication Facility		
NPDES Id. No.	NMR1003Q6	Location:	10200 Bell Avenue SE		
4/6/2021	Owner	Contractor			
Operator	Trumbull Development, LLC.	JB Henderson			
Contact name & title	John Stroud	John Stroud			
e-mail	jstroud@jbhenderson.com	jstroud@jbhenderson.com			
Contact Phone #	505-292-8955	505-292-8955			
COA Inspector	Thomas Evans	Start/End Time:	2:35 PM		
Construction Phase:	Pre-construction				
Type of Inspection:	Regular	Storm Event	Past Storm Event >0.25"	311/Complaint	Follow Up
Weather at time of inspection?	Clear	Temperature:	~	72	
Estimated date of last storm 0.25" or greater	2/22/2021				

Item Number	Deficiency/ Corrective Action			
1	NPDES permit sign not posted.			
2	Silt fence in a couple areas needs to be fully erected at the ends.			
3				
4				
5				
2.1	Discharge off site? (Y/N)	no		
4	Self Inspection Reports	Requested	Latest report Date:	

Notes:	BMP's (silt fence, wattles) have already been installed along South and West fences.
	Machinery is parked on site. Upon leaving the site, a water truck arrived to water down the site.

City of Albuquerque Stormwater Inspector Signature and date:
 Contact information: Thomas Evans (505-803-6215)
tevans@cabq.gov

Thomas Evans 4/7/2021