



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	L20E075	Project Name:	JB Henderson New Fabrication Facility		
NPDES Id. No.	NMR1003Q6	Location:	10200 Bell Avenue SE		
7/14/2021	Owner	Contractor			
Operator	Trumbull Development, LLC.		JB Henderson		
Contact name & title	John Stroud		Jim Kaiser		
e-mail	jstroud@jbhenderson.com		jkaiser@jbhenderson.com		
Contact Phone #	505-292-8955		505-975-1462		
COA Inspector	Thomas Evans		Start/End Time:	11:40 AM-12:15 PM	
Construction Phase:	Earthwork				
Type of Inspection:	☒ Regular	☐ Storm Event	☐ Past Storm Event >0.25"	☐ 311/Complaint	☐ Follow Up
Weather at time of inspection?	Clear		Temperature: ~	84	
Estimated date of last storm 0.25" or greater	7/6/2021				
Item Number	Deficiency/ Corrective Action				
1	Track-out in the streets. Sweep and remove sediment daily.				
2					
3					
4					
5					
2.1	Discharge off site? (Y/N)	no			
4	Self Inspection Reports	Requested	Latest report Date:	None on file	

Notes:	SWPPP is up-to-date. Spoke with Jim Kaiser, and he will have somebody sweep up the track-out as soon as possible. Inspection reports are in the SWPPP

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Thomas Evans (505-803-6215)
tevans@cabq.gov

Thomas Evans 07/14/2021