

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No.	L21E0	074 Project Name:		Farolito Senior Community				
NPDES Id. No.	NMR10				10501 Central Ave NE			
11/	5/2024	Owner						
Operator	•	Farolito Apartments Limited Partnership LLLP Jaynes Corporation						
Contact name & title		Felipe Rael			Shad James			
e-mail		felipe@solhousing.org			shad.james@jaynescorp.com			
Contact Phone #		505-980-5922			505-345-8591			
COA Inspector		Chancellor English			Start/End Time	-		
Construction Phase:					artial land disturbance			
Type of Ir	spection:	Regular	Storm Event	Post Storm	Event >0.25"	311/Complaint	Follow Up	
Weath	er at time of i	nspection?	Clea	nr	Tempe	erature: ~	50	
Estimated date of last storm 0.25" or greater								
Item			Deficienc	y/ Correctiv	e Action			
Number								
	violation of CGP Part 1.5. Required mitigation: You must post a sign or other notice of your permit coverage at a safe, publicly accessible location in close proximity to the construction site per CGP Part 1.5.							
2	Sediment has been tracked out of the site onto Central Ave in violation of CGP Part 2.2.4. Required mitigation: Where sediment has been tracked-out from your site onto paved roads, sidewalks, or other paved areas outside of your site, remove the deposited sediment by the end of the same business day per CGP Part 2.2.4.							
3	The NOI included in the SWPPP is for Greater Albuquerque Housing Partnership and needs to be amended to the Farolito Apartments Limited Partnership LLLP to match the Lease and Building Permit information in violation of CGP Part 1.4.4. The NOI for Jaynes Construction also needs to be included in the SWPPP in violation of CGP Part 7.2.11. Required mitigation: Modify your NOI if there are changes to the name of the operator per CGP Part 1.4.4. Once you are authorized for coverage under the CGP, you must include a copy of your NOI submitted to EPA along with any correspondence exchanged between you and EPA related coverage under the CGP per CGP Part 7.2.11							
2.1	Discharge off site?	(Y/N)	l no	T				
	_		no			10/05/5	00.4	
4	Self Inspect	tion Reports	Yes	Latest rep	oort Date:	10/30/2	024	

Notes:	
Green Glo	be arrived on-site during the City's inspection.

City of Albuquerque Stormwater Inspector Signature and date: 11/8/2024

Contact information: Chancellor English (505) 924-3325

cenglish@cabq.gov

Chancellor English