



# City of Albuquerque Stormwater Construction Site Inspection Report

## General Information

ESC File No.	L21E074	Project Name:	Farolito Senior Community		
NPDES Id. No.	NMIR1005Y8	Location:	10501 Central Ave NE		
3/27/2025	Owner	Contractor			
Operator	Farolito Apartments Limited Partnership LLLP		Jaynes Corporation		
Contact name & title	Felipe Rael		Shad James		
e-mail	<a href="mailto:felipe@solhousing.org">felipe@solhousing.org</a>		<a href="mailto:shad.james@jaynescorp.com">shad.james@jaynescorp.com</a>		
Contact Phone #	505-980-5922		505-345-8591		
COA Inspector	Chancellor English		Start/End Time:	1245pm	
Construction Phase:	verticals				
Type of Inspection:	<input checked="" type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input type="checkbox"/> 311/Complaint	<input type="checkbox"/> Follow Up
Weather at time of inspection?	Clear		Temperature: ~	75	
Estimated date of last storm 0.25" or greater	11/7/2024				
Item Number	Deficiency/ Corrective Action				
1	None				
2.1	Discharge off site? (Y/N)	no			
4	Self Inspection Reports	Yes	Latest report Date:	3/25/2025	

Notes:	
Reports are kept electronically and accessible on-site.	

City of Albuquerque Stormwater Inspector Signature and date: 3/27/2025  
Contact information: Chancellor English (505) 924-3325  
[cenglish@cabq.gov](mailto:cenglish@cabq.gov)

*Chancellor English*