HYDROLOGY

L22/D23D

L22/D23D

L22/10
0230

FIELD REPORT

PROJECT NO.	PROJECT DESCRIPTION	OBSERVER	DATE OBSERVED
	Apartment unit	William R. Peguero	10-9-78
OTHERS PRESENT:	405 Dorado Ct. S.E.		

...on for Field Check: For the drainage of this Apt. unit.

...ription of Field Check Performed: There two ponding area in this Apt. unit. The first one is in the northwest side of the parking lot and the second does the west side of the bldg.

...ngs or Conclusions: At this point the bldg. pond are not finish, but the contractor said that it will be ready 10-12-78.

...up Action required: A follow-up will be needed because the bldg. is not finish.

...sion Date of Field Report to: CITY: A. Vasquez AMAFCA:

William R. Peguero
OBSERVER