

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information													
Project Nar	ne:	BeeHive Homes Four Hills											
Location:		13450 Wenonah Ave SE											
Site Contact Name &		Jason Castillo- S&J Ent.		ESC File No.	. L23E022								
Agency		jasoncastillo88@mail.com		NPDES Id. No.	NMR1001RX								
Inspection Date:		02/27/20 Start/End Time: 0945/1000		45/1000hrs									
	water Inspecto	r:	Fimothy E. Sims		idol								
	ction Phase:												
Type of Ir	nspection: x	Regular	Storm Event	Post Storm	Event >0.25"	311/Complaint	Follow Up						
		5											
Weather at time of i		inspection? Clea storm 0.25" or greater		r	Temper	55*							
Estimated	date of last s	torm 0.25" c	or greater		11/27/2019								
Item		Deficiency / Connecting Action											
Number	Deficiency/ Corrective Action												
1	Please provide the latest SWPPP self-inspection report												
	r lease provide		rrr sen-inspectic	meport									
	BMP's are in place, Please continue to provide SWPPP self-inspections on a 14 day basis until all												
	construction a	ctivity achieve	es completion. Pe	rimeter BMP	's will also requi	re maintanence d	uring this						
	time frame.												
2.1	Discharge off site?	(Y/N)	No										
4	Self Inspect	<mark>tion Reports</mark>	requested	Latest re	eport Date:	12/27/2	019						

Notes:				

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155