

City of Albuquerque Stormwater Construction Site Inspection Report

			General In	nformation
Project Nar	me:	Bee Hive Home		
Location:			enonah SE	ESC File No. L23E022 NPDES Id. No. NMR1001R
Site Contact Name &		Jason Castillo -	S&J Enterpise	Phone: (o)
Agency		jasoncastillo(@gmail.com	Phone: (m)
Owner			- Host Care LLC	Phone: (o) 505-884-6243
Owner's e-mail			r@msn.com	Phone: (m)
Inspection Date:			art/End Time: 11	.30/1145hrs
	water Inspecto	r: Ti	mothy E. Sims	
Construction Phase:			· · · · · · · · · · · · · · · · · · ·	between phases
Type of Ir	nspection: x	Regular	Storm Event	Post Storm Event >0.25" 311/Complaint Follow Up
\A/+ -			Clas	Taganagatura 0 00*
Weath	er at time of i	nspection? :torm 0.25" or	Clea	
Estimated	i date of last s	torm 0.25 or	greater	6/1/2020
Item			Deficienc	y/ Corrective Action
Number			Delicienc	y/ Corrective Action
	Please provide	latect SM/DDD	self-inspection re	anort
1				
The last inspection report on file is dated 12/27/2019				27/2019. Reports will need to be submitted until
	final stabilizati	ion is complete	•	
2.1	Discharge off site?	(Y/N)	No	
4	Self Inspect	tion Reports	requested	Latest report Date: 12/27/2020
	Jen mapee	пон перона	requested	12/27/2020
Neter	I			
Notes:				

 $\hbox{City of Albuquerque Stormwater Inspector Signature and date:} \\$

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

07/07/20