

City of Albuquerque Stormwater Construction Site Inspection Report

General Information						
ESC File No.	M09E012		Project Name:		Sage Plaza	
NPDES Id. No.	,		Location:		1125 Snow Vista Blvd	
10/30/2023		Owner			Contractor	
Operator		Goodman Realty RVT			Cornerstone Contractors	
Contact name & title		Scott Goodman			Joseph Nevarez	
e-mail		sgoodman@goodmanrealty.com			joseph@cornerstoneNM.com	
Contact Phone #		505-441-2354			505-385-7746	
COA Inspector		Chancellor English			Start/End Time	
Construction Phase:		infrastructure				
Type of Inspection:		Regular	Storm Event	Post Storm	Event >0.25"	311/Complaint Follow Up
Weath	er at time of i	nspection? Clear			Temperature: ~ 50	
Estimated date of last storm 0.25" or greater 9/14/2023						
Item	Defining of Competing Antion					
Number	Deficiency/ Corrective Action					
1	The contractor was not identified in the SWPPP. The stormwater team needs to be identified by name					
	and have contact information. A record of training or training certificates for the stormwater team was					
	missing. The SWPPP map was not current by not showing the areas left undisturbed.					
	inissing. The Swerr map was not current by not showing the aleas left undisturbed.					
2.1	Discharge off site?	(Y/N)	no			
4	Self Inspec	tion Reports	Yes	Latest re	port Date:	10/18/2023

Notes: In accordance with City Ordinance § 14-5-2-11(C)(1), self-inspections must continue until the site is "determined as stabilized by the city." The property owner/operator is responsible for determining when the "Conditions for Terminating CGP Coverage" per CGP Part 8.2 are satisfied and then for filing their Notice of Termination (NOT) with the EPA. Each operator may terminate CGP coverage only if one or more of the conditions in Part 8.2.1, 8.2.2, or 8.2.3 has occurred. After filing the NOT with the EPA, the property owner is responsible for requesting a Determination of Stabilization from the City.