City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	M09E031	Project Name:	Solare Collegiate Charter School Phase 3
NPDES Id. No.	NMR1006UK	Location:	8801 Gibson Blvd SW

1/15/2026	Owner	Contractor
Operator	Solare Collegiate Foundation	Insight
Contact name & title	Rachel Sewards	Dave Brown
e-mail	rsewards@solarecollegiate.org	dave@insightnm.com
Contact Phone #	505-917-6442	505-888-7927

COA Inspector	**Chancellor English**	Start/End Time:	11am
Construction Phase:	verticals and interiors		

Type of Inspection:	Regular	Storm Event	Post Storm Event >0.25"	311/Complaint	Follow Up

Weather at time of inspection?	Clear	Temperature: ~	55
Estimated date of last storm 0.25" or greater		1/8/2026	

Item Number	Deficiency/ Corrective Action			
1	None - see note below re construction exit.			
2.1	Discharge off site? (Y/N)	no		
4	Self Inspection Reports	OK	Latest report Date:	12/18/2025

Notes:
The construction exit is full of dirt and will need maintenance soon.
The SWPPP is in the construction office conex.

City of Albuquerque Stormwater Inspector Signature and date: 1/15/2026

Contact information: Chancellor English (505) 924-3325

cenglish@cabq.gov

Chancellor English