



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	M09E032	Project Name:	Sombra del Oeste		
NPDES Id. No.	NMR1005WH	Location:	Gibson Blvd and Valley Cottonwood SW		
2/3/2025	Owner		Contractor		
Operator	Homewise Inc.		Shane		
Contact name & title	Eugene Chavez		Shane Meihaus		
e-mail	echavez@homewise.org		shane@compassnm.com		
Contact Phone #	505-983-9473		505-221-6003		
COA Inspector	James Hughes		Start/End Time:	10am	
Construction Phase:	Retaining walls and Utilities.				
Type of Inspection:	☒ Regular	☐ Storm Event	☐ Post Storm Event >0.25"	☐ 311/Complaint	☐ Follow Up
Weather at time of inspection?	Clear		Temperature: ~	45	
Estimated date of last storm 0.25" or greater	11/7/2024				

Item Number	Deficiency/ Corrective Action				
1	none				
2					
	Discharge off site? (Y/N)	No			
	Self Inspection Reports	OK	Latest report Date:	1/15/2025	

Notes:	
The SWPPP is located in a box on a pole on the east side of the site.	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: James Hughes
jhughes@cabq.gov

2/4/25
James D. Hughes