



City of Albuquerque Stormwater Construction Site Inspection Report

General Information					
ESC File No.	M09E032	Project Name:	Sombra del Oeste		
NPDES Id. No.	NMR1005WH	Location:	Gibson Blvd and Valley Cottonwood SW		
6/27/2025	Owner	Contractor			
Operator	Homewise Inc.	Shane			
Contact name & title	Eugene Chavez	Shane Meihaus			
e-mail	echavez@homewise.org	shane@compassnm.com			
Contact Phone #	505-983-9473	505-221-6003			
COA Inspector	Chancellor English	Start/End Time:	10:30am		
Construction Phase:	Curbs, prep for paving				
Type of Inspection:	<input checked="" type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input type="checkbox"/> 311/Complaint	<input type="checkbox"/> Follow Up
Weather at time of inspection?	Clear		Temperature: ~	80	
Estimated date of last storm 0.25" or greater	6/25/2025				
Item Number	Deficiency/ Corrective Action				
1	SWPPP - The SWPPP and self inspection reports need to be certified by Homewise, Inc. in violation of CGP Parts 4.7.2 and 7.2.10. Required mitigation: Your signatory must sign and date the SWPPP and each inspection report in accordance with CGP Appendix G, Part G.11 according to CGP Parts 4.7.2 and 7.2.10.				
	Discharge off site? (Y/N)	No			
	Self Inspection Reports	Yes	Latest report Date:	6/18/2025	
Notes:					
The SWPPP is located in a box on a pole at the eastern entrance. The posting is near the western entrance. Previous violations have been mitigated.					

City of Albuquerque Stormwater Inspector Signature and date: 6/27/2025
Contact information: Chanacellor English 505-294-3325
cenglish@cabq.gov

Chancellor English