



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	M09E034	Project Name:	Allsup's Albuquerque, NM		
NPDES Id. No.	NMIR10057C	Location:	9501 Gibson Blvd SW		
1/12/2024	Owner	Contractor			
Operator	BW Gas & Convenience Retail, LLC		Wilger Enterprises		
Contact name & title	Thomas Brown		Scot McLelland		
e-mail	tbrown@brookwoodfinancial.com		betsy@wilger.com		
Contact Phone #	515-422-4040		505-345-2854		
COA Inspector	Chancellor English		Start/End Time:	10:45am	
Construction Phase:	verticals				
Type of Inspection:	<input checked="" type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input type="checkbox"/> 311/Complaint	<input type="checkbox"/> Follow Up
Weather at time of inspection?	Clear		Temperature: ~	95	
Estimated date of last storm 0.25" or greater	6/30/2024				
Item Number	Deficiency/ Corrective Action				
1	None				
2.1	Discharge off site? (Y/N)	no			
4	Self Inspection Reports	Yes	Latest report Date:	6/19/2024	

Notes:	

City of Albuquerque Stormwater Inspector Signature and date: 7/3/2024
Contact information: Chancellor English (505) 924-3325
english@cabq.gov

Chancellor English