



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	M09E035	Project Name:	Take 5 Car Wash Snow Vista
NPDES Id. No.	NMIR1005E4	Location:	98th & Sage
1/24/2025	Owner	Contractor	
Operator	Boing US Holdco, Inc.	Spinoff Construction	
Contact name & title	Jorge Primo Planta	Jimmy Gibson	
e-mail	jorge.planta@drivenbrands.com		
Contact Phone #	919-699-7198	832-654-8008	
COA Inspector	Chancellor English	Start/End Time:	3PM
Construction Phase:	verticals		
Type of Inspection:	Regular	Storm Event	Post Storm Event >0.25"
		311/Complaint	Follow Up
Weather at time of inspection?		Clear	Temperature: ~ 50
Estimated date of last storm 0.25" or greater		1/4/2024	

Item Number	Deficiency/ Corrective Action		
1	The SWPPP has not been certified by both operators' signatory in violation of CGP Part 7.2.10. The self-inspection reports were signed by the superintendent without a proper Delegations of Authority, and they were not signed by the owner in violation of CGP Part 4.7.2. Required Mitigation The SWPPP, including the SWPPP Map, Self-Inspection Reports, and Corrective Action Reports, must be kept up-to-date per CGP 7.1 and available on-site per CGP 4.7.3, 5.4.3 and 7.3. Your SWPPP, corrective action log, site inspection, and any other compliance documentation required under this permit, must be signed by the same responsible corporate officer that signs the certification statement on your NOI or by a duly authorized representative of that person per CGP Appendix G.11.2.		
2	The Construction Exit was full of sediment and needs reset.		
2.1	Discharge off site? (Y/N)	no	
4	Self Inspection Reports	No	Latest report Date: 1/8/2024

Notes:	
SWPPP is in the construction trailer.	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Doug Hughes (505) 924-3420
jhughes@cabq.gov

1/25/24

James D. Hughes