

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
Project Name:		Premier Mobile Home						
Location:		2700 Broadway SE						
Site Contact Name & Mike Omlo		Mike Omlo	r - 550-6000	ESC File No.	M14E012C2			
Agency		omlorma@comcast.net NPDES Id. No.						
Inspection Date:		03/05/19	3/05/19 Start/End Time: 0730/0745					
CoA Storn	nwater Inspec	tor:		Timothy Sin	ns, Stormwater Inspector			
Presen	t Phase of		Stabilized					
Cons	truction:							
Type of Ir	nspection: x	Regular	Storm Event	Post Storm	Event >0.25" 311/Complaint	Follow Up		
	_					4		
Weath	er at time of i	·			Temperature: ~	38*		
			Clear					
			nce site was F			_		
Clarify am	ount: ( i.e <1	/4" to >3/4"			5, >1/4"			
				spection				
			Maintenan					
CGP	BMP / Activity		or Correctiv	/e	Location and Notes			
Section			Action Required					
1.5	Post a	Notice	Required					
1.5	Provide and maintain Na							
2.2.1	Waters of the US <50ft.	/						
2.2.3	Sediment control alo	no						
2.2.3	Sediment control alo	ng						
2.2.3	Sediment control along an							
2.2.3	Sediment control alo	ng any pe	· ·					
2.2.3	Sediment control alo	ng any perim		4				
2.2.3	Sediment control along any perimete.							
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter			Stabilized				
2.2.3	Sediment control along any perimeter		Ø <u> </u>					
2.2.3	Sediment control along any perimeter			\				
2.2.3	Sediment control alo	ng any perimeter		F6.				
2.2.3	Sediment control alo	ng any perimeter		~				
2.2.3	Sediment control alo	ng any perimeter		\				
2.2.3	Sediment control alo	ng any perimeter						
2.2.3	Sediment control alo	ng any perimeter						
2.2.3	Sediment control alo	ng any perimeter						
2.2.3	Sediment control alo	ng any perimeter						
224	A 4:-:		1		_			

2.2.5	Manage stock piles			
2.2.6	minimize dust			
2.2.10	Protect storm drain inlets			
2.2.10	Protect storm drain inlets			
2.2.11	Minimize erosion of conveyance channels			/
2.2.12	Sediment Basins			
2.2.14	Stabilize exposed portions of the site			
2.2.14	Stabilize exposed portions of the site			
2.2.14	Stabilize exposed portions of the site			
2.2.14	Stabilize exposed portions of the site			
2.3.1	Equipment and vehicle fueling			
2.3.2	Equipment and vehicle washing			
2.3.3	Building material storage			
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage			
2.3.3	Construction and domestic wastes			
2.3.3	Construction and domestic wastes			
2.3.4	Washing applicators used for paint, stucco, concrete, etc.			
2.3.4	Washing applicators used for paint, stucco, concrete, etc.			
2.3.4	Washing applicators used for paint, stucco, concrete, etc.			
2.4	Dewatering			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports		Latest report Date:	

Notes: (City Inspector Use) Items in compliance can be left blank.

Maintenance or corrective actions are to be completed within seven (7) days.

Notes:					
Notes: Site is stabilized					

City of Albuquerque St		
Contact information:	Timothy Sims, 505-803-6155 or	03/05/19

tsims@cabq.gov

<sup>&</sup>lt;sup>1</sup> Construction General Permit (CGP)