NPDES Tracking No: NMR12_<u>BBS2</u>

ECS File: 15E012C



	General Information		
Project Name and Location	Chick-fil-A Yale an Gibbun		
Site Contact Name & Agency	Chek-fil-d Yale an Gibbun John Pork R&O Construction	Contact Phone #	801 391-5638
Date of Inspection	1-4-16	Start/End Time /2:	00/
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality		
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov		
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One		
Describe Present Phase of Construction	Stokhizor		
Type of Inspection:			
Regular • During stor	rm event • Post-storm event • 311 / Com	plaint Response •	Follow-Up
	Weather Information		
Has there been a storm eyent s	Rain · Sleet · Fog · Snowing · ince the site was Permitted? · Yes · No	Windy	perature: ~_ 3 fF°
Amount: • < 1/4" • (1/4") to 3			power for the contract of the contract of the
	Erosion & Sediment Control Inspec	ction	
Check any BMPs that ha	your Save FAILED or REQUIRE MAINTENANCE		
 Sediment Controls / Silt F Check Dams, Waddles 	, etc.		
Erosion Controls / Mulch, Seed, 5 ml wh			
 Wind Blown Erosion 	V9		
 Housekeeping / Pollutant 	Controls M		
•			
Is site being maintained in complian	nce with Const. Gen. Permit ?* Vel. * No Si	ignature	1.4~163 Date

ECS File: M15 E012 & C



General Information				
		2.2.2.		
Project Name and Location	Chick-fit-A. Gibson an Conventa			
	Gibson an Converty			
		G Di !!	861-391-5630	
Site Contact Name & Agency	P&O Construction	Contact Phone #	-01-37-36-0	
Date of Inspection	17-16-15	Start/End 7.3	55 /10221	
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality			
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov			
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One			
Describe Present Phase of Construction	blds constructor, curbs poured			
Type of Inspection:				
Regular • During stor	rm event • Post-storm event • 311 / Com	plaint Response •	Follow-Up	
	Weather Information			
Weather at time of this inspect			perature: ~_35 F°	
		Windy		
Has there been a storm event since the site was Permitted? Yes No Amount: • < 1/4" • /4" to 3\" • > 34" • Snow"				
Erosion & Sediment Control Inspection				
Check any BMPs that have FAILED or REQUIRE MAINTENANCE Soult of Sike (Skerg +18)				
• Entrance / Off Tracking neds ~ Cran & & Boent & Brop				
Check any BMPs that have FAILED or REQUIRE MAINTENANCE Chit - L1-4 old, enhance soult of Site (Skingard) Entrance / Off Tracking Sediment Controls / Silt Fence, Check Dams, Waddles, etc. Silt fine alm University Blil av an Sawk				
Erosion Controls / Mulch, Seed,				
• Wind Blown Erosion				
Housekeeping / Pollutant Controls 3 back				
- walker such w/ Jan				
Is site being maintained in compliance with Const. Gen. Permit? Yes No Cut C. Chew 11-16-11 Signature Date				

NPDES Tracking No: NPDES Tracking No.

ECS File: MISEUZ C



General Information				
Project Name and Location	Chick-Sil-A Gubson and University	ESC PERMI	IT #	
Site Contact Name & Agency	Dair fork REO constructori		ne#	801-391-5638
Date of Inspection	e-25-15	Start/End Time	910	15/9:35
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality			
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov			
Inspector Qualifications	Stormwater USA			
Describe Present Phase of Construction	Fin grade blig roughed in			
Type of Inspection: Regular · Drive-By/R	,		311/0	Complaint Response
Collow-Up	andom During storm event 1 out stor			
	Weather Information			
Weather at time of this inspection? Clear • Cloudy • Rain • Sleet • Fog • Snowing • High Winds • Other:				
Has there been a storm event since the site was Permitted? · Yes · No				
Amount: • < 1/4" • 1/4" to 3/4" > 3/4" Intensity: • Light • Med. • Hvy. • Snow"				
Erosion & Sediment Control Inspection				
Check any BMPs that have FAILED or REQUIRE MAINTENANCE				
* Entrance / Off Tracking				
Sediment Controls / Silt Fence, Check Dams, Waddles, etc.				
• Erosion Controls / Mulch, Seed,				
• Wind Blown Erosion				
Housekeeping / Pollutant Controls				
•				
Is site being maintained in compliance with Const. Gen. Permit? Yes No With a Chun g-25-1- Signature Date				

NPDES Tracking No: NAPID B852 , NAPID BSS 1 - 9 Kons Gar

ECS File: MISEOIDC



	General Information			
Project Name and Location	Chick-Sil-A Gibson & Campsity	ESC PERM	IT#	
Site Contact Name & Agency	Pair Park Rev Construction			Bul - 391 - 5130
Date of Inspection	8-7-15	Start/End Time	9:55	10:25
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality			
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov			
Inspector Qualifications	Stormwater USA			
Describe Present Phase of Construction Type of Inspection: Type of Inspection:				
Regular · Drive-By/Random · During storm event · Post-storm event · 311 / Complaint Response Follow-Up				
Weather Information				
Weather at time of this inspection? Clear Cloudy Rain Sleet Fog Snowing High Winds Other:				
Has there been a storm event since the site was Permitted? · Yes · No				
Amount: • < 1/4" • 1/4" to 3/4" • > 3/4" Intensity: • Light • Med. • Hvy. • Snow"				
Erosion & Sediment Control Inspection				
Check any BMPs that have FAILED or REQUIRE MAINTENANCE				
Entrance / Off Tracking New entrance - 1. track - out				
Sediment Controls / Silt Fence, Check Dams, Waddles, etc.				
Erosion Controls / Mulch, Seed,				
* Wind Blown Erosion NO (vacate washout in N/2 coul				
Housekeeping/Pollutant Controls 5hll 5rme drash but way bette				
	***		1	
Is site being maintained in compliance with Const. Gen. Permit ?* Yes (N) Signature Date				

From:

Cherne, Curtis

Sent: To:

Friday, August 07, 2015 12:53 PM jairp@randoco.com; Josh Skarsgard

Subject:

SWPPP inspectio chick-fil-a

Attachments:

concrete-washout.jpg

Jair,

Thanks for taking the time to speak with me today.

I like the new construction entrance and the site had considerably less trash. Thanks. However, there was some in the southeast corner.

Things were going pretty good until I came across the concrete wash-out.

Per our discussion you will remove it within seven days.

See ya in about a week.

Curtis Cherne, PE Stormwater Quality COA 924-3420 NPDES Tracking No: NAPIZBB52, NA PIZBS52

City of Albuquerque Stormwater Construction Site Inspection Report

ECS File: MIS B012C

General Information				
Project Name and Location	Chick-Fil-A. Gibson and University	ESC PERM	IT#	nja
Site Contact Name & Agency	Jair Park-sprintendat RLO construction	Contact Pho	ne#	Cell 901-391-5638
Date of Inspection	7-29-15	Start/End Time	9:	20/9:45
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality			
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov			
Inspector Qualifications	Stormwater USA			
Describe Present Phase of Construction	rough graded installin whi	itro		
Type of Inspection: Regular Drive-By/Random During storm event Post-storm event 311 / Complaint Response Follow-Up				
Tollow-op	Weethou Information			
Weather Information				
Weather at time of this inspection? • Clear Cloudy • Rain • Sleet • Fog • Snowing • High Winds • Other:				
Has there been a storm event since the site was Permitted? Yes No				
Amount: • < 1/4" • 1/4" to 3/4"				
Erosion & Sediment Control Inspection				
Check any BMPs that have FAILED or REQUIRE MAINTENANCE Constriction entrances full of Sodium - needs maintenance Entrance / Off Tracking Sodium in Valuesity Block				
incert neur Southern pent had sedinant in 74				
Sediment Controls / Silt Fence, Check Dams, Waddles, etc. Silt fence had me area Not Tools-in				
* Erosion Controls / Mulch, Seed, NO				
* Wind Blown Erosion				
Housekeeping / Pollutant Controls trash (n numrous places on 5 the				
· wrong supply on site				
Is site being maintained in complian		gnature		7-19-U Date

From:

Cherne, Curtis

Sent:

Wednesday, July 29, 2015 2:33 PM

To:

'jairp@randoco.com'; 'tylerc@randoco.com'

Cc:

'josh@skargardfirm.com'

Subject: Attachments: SWPPP inspection Chick-fil-A 1600 University Tracking number NMR12B852, NMR12B55 tentrance.jpg; sediment-university.jpg; sediment-university2.jpg; silt-fence.jpg; trash.jpg; trash.

pile.ipc

Jair,

We spoke onsite this morning.

The following non-compliance issues were found on your site during this morning's SWPPP inspection.

- 1. Lots of trash all over the place.
- 2. The construction entrance was full of sediment and did not appear to have filter cloth underneath it. It's a redo.
- 3. There was sediment in University Blvd and on the sidewalk along University Blvd. It is to be removed.
- 4. The silt fence around the periphery looked fairly new and was toed-in in most locations. However, there was one location along University Blvd. where it was above grade and a portion of the site was draining to that location.
- 5. The inlet near the southern pond had sediment in it and the grate had sediment on it. The inlet is to be cleaned out. The sediment on top is also be removed as it will fall in.
- 6. The SWPPP that was onsite was for "Gibson Rising" or something like that, which was for the rough grading of the larger project. As the project proceeds you will need to implement the BMPs, or similar, that are shown on the approved Erosion and Sediment Control Plan, Merrick and Company Stamp Date 4-27-15, that has the project boundaries for the Chick-Fil-A. It appeared that Red Shamrock, LLC is the property owner. Mr. Skarsgard has been copied on this e-mail.

I have attached photos.

In addition, the steep slopes along the western edge are holding together pretty well now. However, it will not take much rainfall for them to slump-off and require increased maintenance of the silt fence. The City recommends grading a swale between the silt fence and higher area.

As mentioned on-site, mitigation is to occur within 7 days.

If you have any questions, I can be reached at 924-3420.

Curtis Cherne, PE Stormwater Quality Engineer City of Albuquerque

From:

Cherne, Curtis

Sent:

Wednesday, July 29, 2015 2:43 PM 'joah@skarsgardfrim.com' corrected NPDES Tracking number

To:

Subject:

Josh,

I incorrectly noted the wrong tracking number in my previous e-mail. It should have been NMR12B551.

Curtis



City of Albuquerque

Planning Department

Development & Building Services Division

DRAINAGE AND TRANSPORTATION INFORMATION SHEET

(REV 02/2013)

MISEOIZC

Project Title: Chick-fil-A Gibson	Building Permit #: 201493225 City Drainage #:
DRB#: EPC#:	Work Order#:
Legal Description: See Attached	
City Address: 1600 Gibson Blvd SE	
Engineering Firm: Merrick & Company	Contact: Troy Kelts
Address: 5970 Greenwood Plaza Blvd, Greenv	vood village, CO 80015
Phone#: 303-751-0741 Fax#: 30.	3-752-4451 E-mail: troy.kelts@merrick.com
Owner: Chick-fil-A	Contact: Ryan Robinson
Address: PO Box 270571, San Diego, CA 9	
Phone#: 760-522-9764 Fax#:	E-mail: rrobinson@4gdev.com
Architect: CRHO	Contact: Kimanh Nguyen
Address: 195 South "C" Street 200, Tustin, CA	192780
711 021 1021	E-mail: kimanh@CRHO.com
Surv_Tek Inc	Russ Hugo
O38/ Valley View Drive	Contact: Contact
Audiess.	E-mail: russhugg@survtek.com
Phone#: Fax#:	E-mail: russnugg@survtek.com
Contractor: TBD	Contact:
Address:	
Phone#: Fax#:	E-mail:
TYPE OF SUBMITTAL:	CHECK TYPE OF APPROVAL/ACCEPTANCE SOUGHT:
DRAINAGE REPORT	SIA/FINANCIAL GUARANTEE RELEASE
DRAINAGE PLAN 1st SUBMITTAL	PRELIMINARY PLAT APPROVAL
DRAINAGE PLAN RESUBMITTAL	S. DEV. PLAN FOR SUB'D APPROVAL
CONCEPTUAL G & D PLAN	S. DEV. FOR BLDG. PERMIT APPROVAL
X GRADING PLAN	SECTOR PLAN APPROVAL
EROSION & SEDIMENT CONTROL PLAN (ESC)	FINAL PLAT APPROVAL
ENGINEER'S CERT (HYDROLOGY)	CERTIFICATE OF OCCUPANCY (PERM)
CLOMR/LOMR	CERTIFICATE OF OCCUPANCY (TCL TEMP)
TRAFFIC CIRCULATION LAYOUT (TCL)	FOUNDATION PERMIT APPROVAL
ENGINEER'S CERT (TCL)	BUILDING PERMIT APPROVAL
ENGINEER'S CERT (DRB SITE PLAN)	GRADING PERMIT APPROVAL SO-19 APPROVAL
ENGINEER'S CERT (ESC)	A PAVING PERMIT APPROVAL A ESC PERMIT APPROVAL
SO-19	WORK ORDER APPROVAL ESC CERT. ACCEPTANCE
OTHER (SPECIFY)	GRADING CERTIFICATION OTHER (SPECIFY)
WAS A PRE-DESIGN CONFERENCE ATTENDED:	X Yes No Copy Provided
DATE SUBMITTED: January 23, 2015	By: Ryan Robinson (760)522-9764 rrobinson@4gdev.com

Requests for approvals of Site Development Plans and/or Subdivision Plats shall be accompanied by a drainage submittal. The particular nature, location, and scope to the proposed development defines the degree of drainage detail. One or more of the following levels of submittal may be required based on the following

- 1. Conceptual Grading and Drainage Plan: Required for approval of Site Development Plans greater than five (5) acres and Sector Plans
- 2. Drainage Plans: Required for building permits, grading permits, paving permits and site plans less than five (5) acres
- 3. Drainage Report: Required for subdivision containing more than ten (10) lots or constituting five (5) acres or more
- 4. Erosion and Sediment Control Plan: Required for any new development and redevelopment site with 1-acre or more of land disturbing area, including project less than 1-acre than are part of a larger common plan of development

From: Sent: Jair Park <jairp@randoco.com> Wednesday, July 29, 2015 2:45 PM

To:

Cherne, Curtis

Subject:

RE: SWPPP inspection Chick-fil-A 1600 University Tracking number NMR12B852,

NMR12B557

It was good to meet you today! I have already been in contact with my BMP contractor to get all these items up to standard. And also my office so that we can get our SWPPP on the books to maintain our own site. Thank you for the answers to all my questions.

From: Cherne, Curtis [mailto:CCherne@cabq.gov]

Sent: Wednesday, July 29, 2015 2:33 PM

To: Jair Park; Tyler Coley **Cc:** 'josh@skargardfirm.com'

Subject: SWPPP inspection Chick-fil-A 1600 University Tracking number NMR12B852, NMR12B557

Jair.

We spoke onsite this morning.

The following non-compliance issues were found on your site during this morning's SWPPP inspection.

- 1. Lots of trash all over the place.
- 2. The construction entrance was full of sediment and did not appear to have filter cloth underneath it. It's a redo.
- 3. There was sediment in University Blvd and on the sidewalk along University Blvd. It is to be removed.
- 4. The silt fence around the periphery looked fairly new and was toed-in in most locations. However, there was one location along University Blvd. where it was above grade and a portion of the site was draining to that location.
- 5. The inlet near the southern pond had sediment in it and the grate had sediment on it. The inlet is to be cleaned out. The sediment on top is also be removed as it will fall in.
- 6. The SWPPP that was onsite was for "Gibson Rising" or something like that, which was for the rough grading of the larger project. As the project proceeds you will need to implement the BMPs, or similar, that are shown on the approved Erosion and Sediment Control Plan, Merrick and Company Stamp Date 4-27-15, that has the project boundaries for the Chick-Fil-A. It appeared that Red Shamrock, LLC is the property owner. Mr. Skarsgard has been copied on this e-mail.

I have attached photos.

In addition, the steep slopes along the western edge are holding together pretty well now. However, it will not take much rainfall for them to slump-off and require increased maintenance of the silt fence. The City recommends grading a swale between the silt fence and higher area.

As mentioned on-site, mitigation is to occur within 7 days.

If you have any questions, I can be reached at 924-3420.

Curtis Cherne, PE Stormwater Quality Engineer City of Albuquerque