

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
ESC File No.	M15E0			Panda Express			
NPDES Id. No.	Non			2040 Gibson Blvd SE			
	2/13/2025		Owner Lot C-2		Owner Lot C-1		
Operator		CFT NV Developments, LLC Derek Knight			I25 & Gibson LLC Wes Butero		
Contact name & title		_			wes@mdgrealestate.com		
e-mail Contact Phone #		derek.knight@pandarg.com 626-799-9898			505-228-2149		
COA Inspector		Chancellor English			Start/End Time: 12pm		
-					ΙΖΡΙΙΙ		
Construction Phase: Type of Inspection:				foundation Event >0.25" 311/Complaint Follow Up			
					Temperature: ~ 55		
<u> </u>							
Estimated	date of last s	torm 0.25" or greater			11/7/2024		
Item	Deficiency/ Corrective Action						
Number	Deficiency/ Corrective Action						
1	NOI - Construction activity has started before City SWQ Approval, the City has no NOI or ESC Plan on						
		ecord in violation of City Ordinance §14-5-2-11. Required mitigation: For projects that disturb one					
		· · · · · · · · · · · · · · · · · · ·					
	acre or more, or less than one acre but are part of a common plan of development exceeding the property owner is to provide the CGP Notice of Intent documentation that contains the powner name and contact information a minimum of 14 days prior to earth disturbance and p						
	obtaining Work Order or Building Permit approval per City Ordinance §14-5-2-11(A).						
2	Posting - Permit postage coverage was missing from the site in violation of CGP Part 1.5. Required						
	mitigation: You must post a sign or other notice of your permit coverage at a safe, publicly accessible						
	location in close proximity to the construction site. The notice must be located so it is visible from the						
	public road that is nearest to the active part of the construction site, and it must use a font large						
	enough to be readily viewed from a public right-of-way per CGP Part 1.5.						
	lenough to be i	shought to be readily viewed from a public right of way per ear rare 1.3.					
	CWDDD. The CWDDD and celf increation was also were considered in the constant of the constant						
3	SWPPP - The SWPPP and self-inspection reports were unavailable during the inspection in violation of						
	CGP Parts 4.7.3 and 7.3. Required mitigation: You must keep a copy of the current SWPPP and all						
	copies of inspection reports at the site or at an easily accessible location so that they can be made						
	immediately available at the time of an on-site inspection per CGP Parts 4.7.3 and 7.3.						
4	BMPs - A stockpile on the pavement of the neighboring property (Lot C-1) has no stormwater controls						
	to prevent being washed into the City's curb and gutter storm system in violation of CGP Parts 2.1.3						
	and 2.2.3. Required mitigation: Complete installation of stormwater controls by the time each phase						
	of construction activities has begun per CGP Part 2.1.3. By the time construction activity in any given						
	portion of the site begins, install and make operational any downgradient sediment controls that						
	control discharges from the initial site clearing, grading, excavation, and other earth-disturbing						
	activities. Install sediment controls along any perimeter areas of the site that are downslope from any						
	exposed soil or other disturbed areas per CGP Part 2.2.3.						
2.1	Discharge off site?	(Y/N)	no	1.1.		N1/2	
4	Self Inspect	ion Reports	No	Latest re	oort Date:	N/A	
	ı						

City of Albuquerque Stormwater Inspector Signature and date: 2/19/2025

Contact information: Chancellor English (505) 924-3325

Notes:

cenglish@cabq.gov

Chancellor English