

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
Project Name: Sunport Park Hospitality - Comfort Suites							
Location:	iic.	Woodward SW Lot 2-A-2					
Site Contact Name &		Rick 505-713-0053 ESC File No.					
Agency		Yogash - rne.hms@gmail.com NPDES Id. No. M15E023G		î			
Inspection Date:			tart/End Time: 09	50/1015hrs			ļ
CoA Stormwater Inspector: Timothy E. Sims							
	tion Phase:	interior and site work					
Type of Inspection: x Regular Storm Event Post Storm Event >0.25" 311/Complaint Follow Up							Follow Up
Weathe	er at time of i	nspection?	Clea	r	Tempe	rature: ~	46* 71*
Estimated	date of last s	torm 0.25 0	rgreater			6/1/2020	/1
Item	Deficiency/ Corrective Action						
Number	Denciency/ corrective Action						
1	Please provide latest SWPPP self-inspection report						
2	Waste not in acceptable contianer on site and on the east and west lots. Mitigate waste not						
	and utilize provided refuse containers.						
3	Mitigate washouts on site and on west property.						
2.1	Discharge off site?	(Y/N)	No				
4	Self Inspect	tion Reports	requested	Latest rep	ort Date:	2/18/20	)20

Notes:		

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155