

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information									
Project Name:		Sunport Park Hospitality - Comfort Suites							
Location:		Woodward SW Lot 2-A-2							
Site Contact Name &		Rick 505-713-0053 ESC File No.							
Agency		Yogash - rne.ł	nms@gmail.com	NPDES Id. No. M15E023G					
Inspection Date:		08/05/20 Start/End Time: 1100/1130hrs							
CoA Stormwater Inspector: Timothy E. Sims									
Construction Phase:		interior and site work							
Type of Inspection: x		Regular	Storm Event	Post Storm Event >0.25" 311/Complaint Follow Up					
Weath	er at time of i	inspection? Clea		ar	r Temperature: ~ 86*				
Estimated	date of last s	torm 0.25" o	r greater			7/25/2020			
Item									
			Deficienc	y/ Correctiv	e Action				
Number									
	no issues observed with this inspection								
	***Please forward the latest SWPPP self-inspection report.								
2.1	Discharge off site?	(Y/N)	No						
4	Self Inspect	tion Reports		Latest rep	oort Date:	6/10/20	020		

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155