

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
Project Name:		Sunport Park Hospitality - Comfort Suites						
Location:	ocation: Woodward SE Lot 2-A-2, Block 2							
Site Contact Name &		Yogash Kumar, Nicholas		ESC File No.	M15E023G			
Agency		rne.hms@gmail.com		NPDES Id. No.				
Inspection Date:		03/21/19 Start/End Time: 1						
CoA Stormwater Inspec		ctor:		Timothy Sim	ns, Stormwater Inspector			
Present Phase of		vertical wood frame						
Construction:								
Type of Inspection: Regular Storm Event Post Storm Event >0.25" 311/Complaint x Follow Up								
Weather at time of inspection? Temperature: ~ 48*								
weathe					Temperature: ~ 48*			
Llasth		Cloudy/Windy						
	ere been a ste ount: (i.e <1		nce site was P		> 1 / 4 !!			
Clarify am	5, >1/4"							
			Ins Maintenanc	pection				
			or Correctiv					
CGP	BMP / Activity		Action		Location and Notes			
Section			Required					
1.5	Post a Notice		x	Please pro	ovide NPDES posting and permit number			
2.2.1	Provide and maintain Natural buffer when Waters of the US <50ft.							
2.2.3	Sediment control along any perimeter		х	silt fence on	north and west border requires maintenance			
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter		х	re-	install silt fence where damaged			
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.4	Minimize sediment t	rack out						

2.2.5	Manage stock piles					
2.2.6	minimize dust					
2.2.10	Protect storm drain inlets					
2.2.10	Protect storm drain inlets					
2.2.11	Minimize erosion of conveyance channels					
2.2.12	Sediment Basins					
2.2.14	Stabilize exposed portions of the site					
2.2.14	Stabilize exposed portions of the site					
2.2.14	Stabilize exposed portions of the site					
2.2.14	Stabilize exposed portions of the site					
2.3.1	Equipment and vehicle fueling					
2.3.2	Equipment and vehicle washing					
2.3.3	Building material storage					
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage					
2.3.3	Construction and domestic wastes	х	littler and construction debris requires cleaning			
2.3.3	Construction and domestic wastes	х	Please provide the ability to cover dumpster			
2.3.4	Washing applicators used for paint, stucco, concrete, etc.					
2.3.4	Washing applicators used for paint, stucco, concrete, etc.					
2.3.4	Washing applicators used for paint, stucco, concrete, etc.					
2.4	Dewatering					
2.1	Discharge off site? (Y/N)	No				
4	Self Inspection Reports	requested	Latest report Date:			
Notos: (City	v Inspector Lise) Items in compliance can be left blank					

Notes: (City Inspector Use) Items in compliance can be left blank.

¹ Construction General Permit (CGP)

Maintenance or corrective actions are to be completed within seven (7) days.

Notes: self inspection reports are requested at this time please e-mail to me

3/12/2019 a storm event >0.25" occurred. Provide self-inspection report.

City of Albuquerque Stormwater Inspector Signature and date:

Contact information:

ion: Timothy Sims, 505-803-6155 or tsims@cabq.gov 03/21/19