

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
Project Name:		Comfort Suites						
Location:		1401 Woodm	1401 Woodmont SE Nick Eveleigh ESC File No. M15E023G					
Site Contact Name &		Nick Eveleigh	Nick Eveleigh			M15E023G		
Agency			Yogash Kumar			NMR12BH30		
Inspection Date:			tart/End Time:	1:00/1:30				
CoA Stormwater Inspector: Curtis Cherne								
	tion Phase:		vertical, installing utilities Regular Storm Event Post Storm Event >0.25" 311/Complaint					
Type of Ir	spection:	K Regular	Storm Event	Post Storm	Event >0.25"	311/Complaint	Follow Up	
Month	r at time of	finenestion?	Clo	udu	Tompo	raturo: ~	80	
Weather at time of inspection? Cloudy Temperature: ~ 80 Estimated date of last storm 0.25" or greater 5/10/2019								
Item	Deficiency/ Corrective Action							
Number								
1	Hole under silt fence SW corner							
2	Grade too high against silt fence along the West side about mid-site							
3	track-out pad requires maintenance							
4	minor track-out							
5	construction and domestic waste not in an acceptable container							
			•••					
						·		
		· · · · · ·						
								
			· ··					
2.1	Discharge off site	? (Y/N)	No					
4	Self Inspe	ection Reports	request	Latest re	port Date:	4/1/20	09	
30								
Notes:								
a portion of the site drains out the corner with the hole under the silt fence								
						5/		
	-							

City of Albuquerque Stormwater Inspector Signature and date:

Contact information:

Curtis Cherne PE, 505-924-3420

ccherne@cabg.gov

06/11/19 Center a Cheme