

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information										
Project Name:			Comfort Suites							
Location:			1401 Woodmont SE							
Site Cont	tact Name &	$\Box$	Nick Eveleigh	ESC File N		M15E023G				
A	gency		Yogash Kuma	NPDES Id. I	No.	NMR12BH30				
Inspection	Date:		06/25/19 Start/End Time:		10:10		10:35			
	water Inspec		: [0	Curtis Cherne						
Construction Phase:							talling utilities			
Type of Inspection:			Regular	Post Sto	Post Storm Event >0.25"   311/Complaint   X Follow U			nt X Follow Up		
									75	
Weatne	er at time o	<u>it ir</u>	nspection? Cloudy torm 0.25" or greater				Temperature: ~ 75			
Estimațed	date of last	t sı	torm 0.25 o	r greater			3/10/2013		NV/750710	
Item				Dofici	angul Corre	activ	o Action		The Bull of	
Number	Deficiency/ Corrective Action									
	Hole under silt fence SW corner									
1	note under sitt tellte sw corner									
		_				_				
	<del> </del>	_								
	<del>[</del>									
								A		
		_					<del></del>			
							<u></u>			
2.1	Discharge off site		(Y/N)	Yes						
4	Self Inspe	ect	tion Reports		Latest	t re	port Date:	6/10	)/2019	
Notes:										
a portion	of the site o	dra	ins out the c	corner with th	ie hole und	er t	he silt fence-	discussed wit	h Rick	
other prev	vious issues	m	itigated							
Rick is to l	nave hole u	nd	er silt fence	fixed and sen	d me pics b	у С	OB Friday 6-2	28-19		

City of Albuquerque Stormwater Inspector Signature and date:

Contact information:

Curtis Cherne PE, 505-924-3420

ccherne@cabq.gov

06/25/19 Cente a chane