

City of Albuquerque Stormwater Construction Site Inspection Report

			General	Information						
ESC File No.	M15E0	E036 Project Name:			Sunport Appartments					
NPDES Id. No.	NMR100				2601 Mulberry SE					
8/19/2020		Property Owner		Contractor						
Operator		Sunprot Apartments LLC			Snider Construction					
Contact name & title		Zack Snyder		Gary Christiansen						
Contact E-mail		Zsnydernm@gmail.com		gchristensen@snyder-const.com						
Contact Phone #		505-250-8595			c 505-720-8475 o 505-923-3181					
COA Inspector		Doug Hughes			Start/End Time	: 7:30/8:	40AM			
Construction Phase:					thwork					
Type of Inspection:		Regular	Storm Event		Event >0.25"	311/Complaint	Follow Up			
	er at time of in			ear	Tempe	rature: ~	84			
Estimated	date of last st	orm 0.25" (or greater							
Item	Deficiency/ Corrective Action									
Number	Denciency/ corrective Action									
1	Track out in str	Track out in street to adjacent lot nw of Site. Remove sediment from ROW same day it occours.								
2	Construction e	Construction entrance muddy. Reset and modify entrance to prevent sediment.								
3	Operator signature missing from SWPPP. All operators must sign.									
4	ESC Plan and property owner's NOI must be approved by the City for all lotsinvolved in this site.									
5	Silt fence is not at limits of disturbance along street and not embeded properly.									
1.1	Discharge off site?	(Y/N)	Yes							
						8/17/2				

Notes:			

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505) 924-3420 jhughes@cabq.gov <mark>8/19/2020</mark> James D. Hughes