

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
ESC File No.	M15E			Sunport Appartments			
NPDES Id. No. NIVIR10					2601 Mulberry SE		
	9/2020	Property Own			Contractor		
Operator		Sunprot Apartments LLC			Snider Construction		
Contact name & title		Zack Snyder			Gary Christiansen		
Contact E-mail		Zsnydernm@ gmail.com			gchristensen@snyder-const.com		
Contact Phone #		505-250-8595			c 505-720-8475 o 505-923-3181		
COA Inspector		Doug Hughes			Start/End Time: 7:30/8:40AM		
Construction Phase:					hwork		
	spection:						Follow Up
Weather at time of inspection? Clear Temperature: ~ 84							
Estimated date of last storm 0.25" or greater							
Item							
Number	Deficiency/ Corrective Action						
1	Track out in street to adjacent lot nw of Site. Remove sediment from ROW same day it occours.						
2	Construction entrance muddy. Reset and modify entrance to prevent sediment.						
3	Operator signature missing from SWPPP. All operators must sign.						
4	ESC Plan and property owner's NOI must be approved by the City for all lotsinvolved in this site.						
5	Silt fence is not at limits of disturbance along street and not embeded properly.						
1.1	Discharge off site?	(Y/N)	Yes				
1.1		tion Reports	163	Latest rer	oort Date:	8/17/2	020
	Sell Hispect	lon Reports		Latestie	Joil Date.	8/1//2	.020
Notes:							

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505) 924-3420

jhughes@cabq.gov