



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	M15E036	Project Name:	Sunport Apartments		
NPDES Id. No.	NMR100385	Location:	Mulberry St. SE		
5/20/2021	Owner			Contractor	
Operator	Sunport Apartments, LLC.		Snyder Construction		
Contact name & title	Zach Snyder		Gary Christensen		
e-mail	zsnydernm@gmail.com		gchristensen@snyder-const.com		
Contact Phone #	505-872-0746		505-720-8475		
COA Inspector	Thomas Evans		Start/End Time:	12:57 PM/1:20 PM	
Construction Phase:	Building Construction				
Type of Inspection:	☒ Regular	☐ Storm Event	☐ Past Storm Event >0.25"	☐ 311/Complaint	☐ Follow Up
Weather at time of inspection?	clear		Temperature:	~ 80	
Estimated date of last storm 0.25" or greater	5/3/2021				
Item Number	Deficiency/ Corrective Action				
1	Holes in silt fence. Repair and maintain silt fences (CGP 2.2).				
2	Reports not signed. Self-inspection reports must be signed by an authorized representative as stated in CGP Appendix I, Section I.11.2				
3	Sediment in the streets. Remove sediment from the streets daily (CGP 2.2.4)				
4					
5					
2.1	Discharge off site? (Y/N)	no			
4	Self Inspection Reports	Requested	Latest report Date:	5/17/2021	

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
 Contact information: Thomas Evans (505-803-6215)
tevans@cabq.gov

Thomas Evans 05/24/2021