

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
ESC File No.	M15E	E036 Project Name:			Sunport Apartments		
NPDES Id. No. NMR10		DO385 Location:			Mulberry St. SE		
2/22/2023		Owner			Contractor		
Operator		Sunport Apartments, LLC.			Snyder Construction		
Contact name & title		Zach Snyder			Gary Christensen		
e-mail		zsnydernm@gmail.com			gchristensen@snyder-const.com		
Contact Phone #		505-872-0746			505-720-8475		
COA Inspector		Doug Hughes			Start/End Time: 1:30pm		
Construction Phase:		Apartment Bldg cor				t dirt.	
Type of In	spection:	Regular	Storm Event   Past Storm Event >0.25"   311/Complaint   Fo				Follow Up
Weath	er at time of i	nspection? clear			Temperature: ~ 36		
		torm 0.25" or greater			12/4/2022		
Item	Deficiency/ Corrective Action						
Number	Deficiency/ Corrective Action						
1	NOI expired one year ago. Provide new NOI with SWPPP.						
2	SWPPP not available on site at time of inspection Provide a scanned copy of the up-to-date SV						
	with all reports to the Storm Water Quality Section at 600 2nd St NW suite 400 - Jhughes@cabq.gov - Per						
	CGP 4.8.2						
3	Post current CGP coverage on a sign for safe public viewing per CGP						
3							
4	Holes in silt fence. Repair and maintain silt fences (CGP 2.2).						
5							
2.1	Discharge off site?	(Y/N)	no				
4	Self Inspect	ion Reports	Requested	Latest re	port Date:	5/17/20	21
Notes: Left message for Gary Christensen, called Zack Snyder but 872-0746 is out of service and							
250-8595 mailbox is full.							
250 0555 Mandox IS Tulli							

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505-924-3420)

jhughes@cabq.gov