



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	M15E036	Project Name:	Sunport Apartments - Staging yard		
NPDES Id. No.	NMR10039H	Location:	Mulberry St. SE		
5/20/2021	Owner	Contractor			
Operator	Sharif Rabadi A & Samia S Star Trust		Snyder Construction		
Contact name & title	Sharif Rabadi		Gary Christensen		
e-mail	startrustofnm@yahoo.com		gchristensen@snyder-const.com		
Contact Phone #	505-440-6443		505-720-8475		
COA Inspector	Thomas Evans		Start/End Time:	12:50 PM/12:56 PM	
Construction Phase:	Staging				
Type of Inspection:	☒ Regular	☐ Storm Event	☐ Past Storm Event >0.25"	☐ 311/Complaint ☐ Follow Up	
Weather at time of inspection?	clear		Temperature: ~	80	
Estimated date of last storm 0.25" or greater	5/3/2021				
Item Number	Deficiency/ Corrective Action				
1	Sediment in the streets. Remove sediment from the streets daily (CGP 2.2.4)				
2	Domestic waste and debris at inlets. Remove waste and debris and maintain inlet protection (CGP 2.2.10)				
3	Track-out pad has deteriorated. Add additional rock and maintain track-out pad to prevent sediment from exiting the site (CGP 2.2.4)				
2.1	Discharge off site? (Y/N)	no			
4	Self Inspection Reports	Requested	Latest report Date:	5/17/2021	

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Thomas Evans (505-803-6215)
tevans@cabq.gov

Thomas Evans 05/24/2021