City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Space Dynamics Lab Parking Lot		
Location:	1720 Randolph Rd. SE		
Site Contact Name & Agency	Jeff Ware PM	ESC File No.	M15E046
	jeff.ware@sdl.usu.edu	NPDES Id. No.	NMR1002FR
Inspection Date:	01/21/20	Start/End Time:	0940/0945hrs
CoA Stormwater Inspector:	Timothy E. Sims		
Construction Phase:	STABILIZED		

Type of Inspection:	x	Regular		Storm Event		Post Storm Event >0.25"		311/Complaint		Follow Up

Weather at time of inspection?	Rain	Temperature: ~	40*
Estimated date of last storm 0.25" or greater		1/21/2020	

Item Number	Deficiency/ Corrective Action			
	STABILIZED			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports		Latest report Date:	

Notes:	

City of Albuquerque Stormwater Inspector Signature and date: Timothy E. Sims

Digitally signed by Timothy E. Sims
DN: cn=Timothy E. Sims, o=Stormwater Inspectionos, ou=Planning, email=tsims@cabq.gov, c=US
Date: 2020.01.22 07:36:43 -07'00'

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov 01/21/20