



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Space Dynamics Lab Parking Lot				
Location:	1720 Randolph Rd. SE				
Site Contact Name & Agency	Jeff Ware PM jeff.ware@sdl.usu.edu	ESC File No.	M15E046		
		NPDES Id. No.	NMR1002FR		
Inspection Date:	11/20/19	Start/End Time:	0940/0950		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	site work				
Type of Inspection:	☒ Regular	☐ Storm Event	☐ Post Storm Event >0.25"	☐ 311/Complaint	☐ Follow Up

Weather at time of inspection?	Clear	Temperature: ~	55*
Estimated date of last storm 0.25" or greater			

Item Number	Deficiency/ Corrective Action		
	no issues observed with this inspection		
	Please provide the latest SWPPP self-inspection report		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	requested	Latest report Date: 10/2/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 11/20/19