

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No.	M16E0	,			Orion Center			
NPDES Id. No. NMR10		03G0 Location:		SEC of Gibson and Girard				
6/9/2021		Owner			Contractor			
Operator		Hensel Phelps						
Contact name & title		Raul Velez						
e-mail		rvelez@henselphelps.com						
Contact Phone #		602-471-4637				1		
COA Inspector		Thomas Evans			Start/End Time: 11:25 AM-12:05 PM			
Construction Phase:		infrastructure/staging/stockpiling  Regular   Storm Event   Past Storm Event >0.25"   311/Complaint   Follow U					le u	
Type of Inspection:								
	er at time of i				Temperature: ~ 80			
Estimated date of last storm 0.25" or greater 5/31/2021								
Item	Deficiency/Corrective Action							
Number	Deficiency/ Corrective Action							
1	Sediment in the streets. Sweep and remove sediment from the streets daily.							
*	seament in the streets. Sweep and remove seament from the streets daily.							
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspect	ion Report	s Requested	Latest re	port Date:	None or	n file	
				<del>-</del>	•			

Notes: No activity on the East side of Girard. The lot on the West side of Girard is being used for stockpiling. The company doing the work is IPR, LTD. Mike Daniels is the main contact. I spoke with Frank Clark at the site. He said this lot has been used for stockpiling before. There are no BMPs in this area. THIS SITE IS UNDER AVIATION'S INSPECTION AND CONTROL.

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Thomas Evans (505-803-6215)

tevans@cabq.gov

Thomas Evans

06/11/2021