

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
Project Name:		Volterra						
Location:		Juan Tabo &	Rocky Top					
Site Contact Name &		Pulte Team		ESC File No.		M21E018_P		
Agency				NPDES Id. No.		NMR1001Z7		
Inspection Date:				00/0830hrs				
	vater Inspector		Timothy E. Sims					
	tion Phase:		,	Home co	nstruction			
Type of Inspection: x		Regular	Storm Event	Post Storm E		311/Complaint	Follow Up	
,,,			101011111111111111111111111111111111111			10-27 00	, oo op	
Weather at time of inspection? Clear Temperature: ~ 3							37*	
Estimated	date of last s	torm 0.25" or greater			4/13/2020			
						., _0, _0_0		
Item	Deficiency/ Corrective Action							
Number	,,							
	no new issues observed with this inspection							
			1					
2.1	Discharge off site?	(Y/N)	No					
4	Self Inspect	ion Reports	;	Latest ren	ort Date:	4/10/20	)20	
						., ,		
Maria I								
Notes:								

 $\label{lem:city} \textbf{City of Albuquerque Stormwater Inspector Signature and date:}$ 

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

04/15/20\_\_\_\_\_