

City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:		Volterra								
Location:		Juan Pablo & Rocky Top								
Site Contact Name & Agency		Dan Mallak		ESC File No.	M21E018-P					
		Patty Horner		NPDES Id. No.	NMR 1001Z7					
Inspection Date:		4-22-19	Start/End Time:	8:45	9:00					
CoA Stormwater Inspector:			Curtis Cherne							
Construction Phase:		2 vertical, & 3 slabs								
Type of Inspection:	☐	Regular	☐	Storm Event	☐	Post Storm Event >0.25"	☐	311/Complaint	☒	Follow Up

Weather at time of inspection?	windy, clear	Temperature: ~ 55
Estimated date of last storm 0.25" or greater	4-17-19	

Item Number	Deficiency/ Corrective Action		
2.1	Discharge off site? (Y/N)	NO	
4	Self Inspection Reports		Latest report Date: 4-8-19

Notes: 2 vertical, 3 slabs

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Curtis Cherne, 505-924-3420

ccherne@cabq.gov

Conto C per 4-22-19