SLG Holdings

Raylee: Juan Tabo Hills Estates

Storm Water Compliance Inspection Form



PO Box 400 Los Lunas, NM 87042 www.greenglobenm.com

Inspection Type: Routine	Date: 05-15-2020	Time: 7:45 AM				
Permit Tracking #:	Inspector Name: Mario Alderete	Qualifications: Inspector				
Current Weather Conditions:	Date and Amount of Last Recordable Storm Event: 11-21-2019 .75 Inches					

Construction Time Line:

Action	Start Date	Date Complete
Initial BMP Installation	10-23-2019	10-23-2019
Clearing and Grubbing		
Utility Installation		
Construction of Structure		
Final Stabilization		

Site Walk:

Question	Yes	No	N/A	Comment
Is there a proper posting sign?	\boxtimes			Posted on Raylee Marketing Sign
Are areas that have been disturbed, but not under construction been properly stabilized?			\boxtimes	
Velocity Reduction Devices i.e. Check Dams, Berms, Etc.			\boxtimes	
Silt Fence	Χ			
Wattles/Filter Sock	Χ			
Inlet Protection	\boxtimes			
Cut Back Curbs	\boxtimes			
Waste Management	\boxtimes			
Vehicle Tracking Control	\boxtimes			
Material Storage			\boxtimes	
Dust Control			\boxtimes	
Street Sweeping		X		
Construction Washouts i.e. Concrete, Paint, Stucco Etc.	\boxtimes			
Discharge Points	Χ			
Sanitary Stations	\boxtimes			
Stockpiles	\boxtimes			Stock piles in 1800 sunset Stock piles 1813 pepejoy
Other			\boxtimes	

SLG Holdings

Raylee: Juan Tabo Hills Estates

SWPPP Information:

Question	Yes	No	N/A	Comment
Is the SWPPP kept on site?	\boxtimes			
Was the SWPPP updated at the time of the inspection?	\boxtimes			
Are all certification pages signed?	\boxtimes			
Are inspector qualifications in the SWPPP?	\boxtimes			
Is there a copy of the NOI and Acknowledgement letter?	\boxtimes			
Is there a delegation letter in the SWPPP?	\boxtimes			
Was the last inspection/CAL certified?	X			

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Owner: Jeff Grady

Name

Operator:

Signature

Signature

Name
Additional Comments:

Date

Date

Raylee: Juan Tabo Hills Estates



Action Log:

Location	Action Type	Action Required	Date Noted	Date Completed	Initials
Sunset st	Maintenance	Sweep street	04-17-2020		
Ponejoy		Sweep street	04-17-2020		

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Joeate dx 10

Inspector: Mario Alderete Name

Signature

05-15-2020

Date