



# City of Albuquerque Stormwater Construction Site Inspection Report

## General Information

ESC File No.	M21E018_T	Project Name:	Volterra - Juan Tabo Hills		
NPDES Id. No.	NMR1003L0	Location:	11404 Rock Squirrel Ave SE		
4/6/2021	Owner	Contractor			
Operator	Twilight Homes	Twilight Homes			
Contact name & title	Tim Mcnaney	Tim Mcnaney			
e-mail	<a href="mailto:tmcnaney@twilighthomes.com">tmcnaney@twilighthomes.com</a>	<a href="mailto:tmcnaney@twilighthomes.com">tmcnaney@twilighthomes.com</a>			
Contact Phone #	505-975-1154	505-975-1154			
COA Inspector	Thomas Evans	Start/End Time:	2:55 PM/3:25 PM		
Construction Phase:	Vertical				
Type of Inspection:	Complaint	Storm Event	Past Storm Event >0.25"	311/Complaint	
Weather at time of inspection?		Clear/ Windy	Temperature: ~	70	
Estimated date of last storm 0.25" or greater		2/22/2021			
Item Number	Deficiency/ Corrective Action				
1	No violations observed.				
2					
3					
4					
5					
2.1	Discharge off site? (Y/N)	no			
4	Self Inspection Reports	Requested	Latest report Date:	6/30/2020	

Notes:	Inspection conducted as a result of a complaint that a silt fence was blocking an inlet. The storm inlets had wattles protecting the inlets that were properly installed. No silt fence was observed.

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Thomas Evans (505-803-6215)

[tevans@cabq.gov](mailto:tevans@cabq.gov)

*Thomas Evans* 4/7/2021