

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
Project Name:		Cooperative Educational Services						
Location:		10601 Research Rd SW						
Site Contact Name &		Justin- Bradbury Stamm		ESC File No.		M21E021		
Agency		jsantibanez@bradbutystamm.com NPDES Id. No.						
Inspection Date:			art/End Time: 08	800/0820hrs				
CoA Stormwater Inspecto								
Construction Phase:		footings						
Type of Inspection:		Regular	Storm Event x	Post Storm B	Event >0.25"	311/Complaint	Follow Up	
)A/a ath			Class		Tamaa		27*	
Weather at time of i Estimated date of last s		nspection?	Clea	ar	Tempe	rature: ~ 4/14/2020	37*	
Estimated	l date of last s	storm 0.25 0	greater			4/14/2020		
Item	Deficiency/ Corrective Action							
Number	Denciency/ corrective Action							
	no issues observed with this inspection							
	On site rain guage reveals approximately 0.50" event occurred on 04/13/2020. Please provide							
	after storm event inspection.							
2.1	Discharge off site?	(Y/N)	No					
4	Ţ	tion Reports	requested	Latest reg	oort Date:	3/27/20	020	

•

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155