

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
Project Name:		Cooperative Educational Services					
Location:		10601 Research Rd SW					
Site Contact Name &		Justin- Bradbui	ry Stamm	ESC File No.			
Agency			santibanez@bradbutystamm.com NPDES Id. No. NMR1002L6 / NMR1002			02LA	
Inspection Date:				30/1200hrs			
	vater Inspecto	r: Tir	mothy E. Sims				
	tion Phase:		•		tical		_
Type of Inspection: x Regular Storm Event Post Storm Event >0.25" 311/Complaint Follow Up							
347 -1		2	01		-		20*
Weathe	er at time of i	nspection?	Clea	r	Tempe	rature: ~	89*
Estimated	date of last s	torm 0.25" or	greater			7/25/2020	
Item	Deficiency/Corrective Action						
Number	Deficiency/ Corrective Action						
Itamber	no issues observed with this inspection						
	·						
	***Please forward the latest SWPPP self-inspection report.						
			<u> </u>	· ·			
2.1	Discharge off site?	(Y/N)	No				
4	Self Inspect	ion Reports	requested	Latest rep	ort Date:	6/24/20	020
		· · · · · · · · · · · · · · · · · · ·					
Notes:	inspection co	nduc-19ted fo	ollowing Covid-	19 constrai	nts		
-			-				

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov 08/13/20