

You are here: Permits Landing Page 2012 CGP 2012 CGP Details

2012 Construction General Permit eNOI Detail

Quick Jump to Other **Permits**

Details for NMR12B901

General Information

Project / Site Name: **Current Status** Tracking Number Permit Type:

Volterra Villas Submitted To EPA NMR12B901 NO

Super jasrider 1°C dehirton un Jay Grilen

Interview Page Answers

Is your project/site located in Indian Country Lands? Are you requesting coverage under this NOI as a 'federal operator' as defined in Appendix A?

Operator Information

Operator's Name: Street City: State Zip Code: **Point of Contact Name:** Phone Number: Operator Email

IRS Employer Identification Number (EIN):

D.R. Horton Inc 4400 Alameda NE Suite B Albuquerque **New Mexico** 87113 **Brent Lesley** (505) 797-4245 pblesley@drhorton.com

N/A

No

No

Project / Facility Information

Project / Site Name: Street: City: State Zip Code: Project / Facility on Indian Land? Reservation Name:

Volterra Villas N/A Albuquerque **New Mexico** 87116 N/A

Additional Project Information

Charle way, Feedback

12 Construction General Permit

Is your project an 'emergency-related project' as defined in Appendix

Have stormwater discharges from your project/site been covered

previously under an NPDES permit?

Estimated Project Start Date Estimated Project End Date

Have earth-disturbing activities commenced on your project/site? County or Similar government subdivision:

07/30/2015 07/30/2016

No Bernalillo

Latitude and Longitude Information

Longitude

Longitude Unit: Lat tude: Latitude Unit:

Latitude / Longitude Data Source: Horizontal Reference Datum

Estimated Area to be Disturbed (to the nearest quarter acre):

106.5155

(degrees, decimals)

35.0543

(degrees, decimals) Google Earth Unknown

3

Chemical Treatment Information

Will you use polymers, flocculants, or other treatment chemicals at your construction site?

ESA

Under which criterion listed in Appendix D are you eligible for coverage under this permit?

C. Federally-listed threatened or endangered species or their designated critical habitat(s) are likely to occur in or near your site's "action area," and your site's discharges and dischargerelated activities are not likely to adversely affect listed threatened or endangered species or critical habitat. This determination may include consideration of any stormwater controls and/or management practices you will adopt to ensure that your discharges and discharge-related activities are not likely to adversely affect listed species and critical habitat. To make this certification, you must include the following in your NOI: 1) any federally listed species and/or designated habitat located in your "action area"; and 2) the distance between your site and the listed species or designated critical habitat (in miles). You must also include a copy of your site map with your NOI.

Provide the basis for criterion selection selected

1) Any federal listed species and/or designated habitat located in your Rio Grande River

2) The distance between your site and the listed species or designated ~11.1 Miles critical habitat (in miles):

NMED Website and USFWS Website

SWPPP Point of Contact

Name:

Organization Name Phone:

Fav Email **Brent Lesley** D.R. Horton Inc. (505) 797-4245

N/A

pblesley@drhorton.com

Discharge Information

Does your project/site discharge stormwater into a Municipal Separate Yes

Storm Sewer System (MS4)?

Are there any surface waters within 50 feet of your project's earth

disturbances?

Feedback

If a TMDL has been approved or established, identify the title or reference of the TMDL document:

N/A

Impaired Surface Waters to Which you Discharge

Surface water(s) to which you discharge	Impaired Water	Listed Water Pollutant(s)	Tier 2, 2.5 or 3	Source	TMDL Name and Pollutant
Tijeras Arroyo	No		No	NMED Website	
Rio Grande River	Yes	FISH CONSUMPTION ADV	Yes	NMED Website	E Coll

Historic Preservation

Is your project/site located on a property of religious or cultural significance to an Indian tribe? Are you installing any stormwater Yes controls as described in Appendix E that require? (Appendix E, Step 1): If yes, have prior surveys or evaluations conducted on the site have already determined historic properties do not exist, or that prior disturbances have precluded the existence of historic properties? (Appendix E, Step 2): if no, have you determined that your installation of subsurface earthdisturbing stormwater controls will have no effect on historic N/A properties? (Appendix E, Step 3): If no, did the SHPO, THPO, or other tribal representative (whichever applies) respond to you within the 15 calendar days to indicate whether the subsurface earth disturbances caused by the installation of stormwater controls affect historic properties? (Appendix E, Step 4) If yes, describe the nature of their response: N/A

Certifier Information

Name:	Bradley kile
Title	N/A
Email	brkile@drhorton.com
Certified Date	07/21/2015

Preparer Information

Name	Tim Slatunas
Phone:	(505) 353-2558
Fax:	N/A
Organization	SUPERIOR STORMWATER SERVICES LLC
Email:	tim@superlorstormwater.com

Corresponding Documents

File Name	File Size	File Section	Date Uploaded	Download
BMP Plan Volterra Villas.pdf	4585296	ESA Section	21-JUL-15	Download

Back to Search Results 2 Printer Friendly

1 - 1

release 1.0

* .

ECS File: M22 E016 B



	General Information		· 			
Project Name and Location Monachos and Tires Arryo						
Site Contact Name & Agency Brut Usky Contact Phone # 797-42						
Date of Inspection	5-3-16	Start/End Time	2:40/2:55			
Inspector Name, COA Dept.	Curtis Cherne, Sto	ormwater Qu	ality			
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov					
Inspector Qualifications	Qualified Compliance Inspector of Stormwate	er- Stormwater	One			
Describe Present Phase of Construction	Strutt built - 7 hours	11				
Type of Inspection: Regular During stor	rm event • Post-storm event (> 0.5 inch) • 3	11 / Complain	Response • Follow-Up			
	Weather Information					
Weather at time of this inspect	ion?		Temperature: ~_6f F°			
		Windy				
Has there been a storm event s Amount: • < 1/4" • 1/4" to	ince the site was Permitted? · (e) · No 4" · > 34" · Snow"					
Erosion & Sediment Control Inspection						
Entrance/Track-Out NO longue or trachect [2029 court up a worth at entrance						
Sediment Controls / Silt F Check Dams, Waddles	ence,	waffi	- Confraid			
Erosion Controls / Mulch		on it				
* Housekeeping/Pollutant Controls 12035 (1 A						
Debris/Pollutants/Sediment in MS4 Debris/Pollutants/Sediment in MS4						
· Notes Louis recently swept						
Is site being maintained in compliance with the Drainage Ordinance ? " Yes " No						



From:

Cherne, Curtis

Sent:

Wednesday, June 10, 2015 2:43 PM

To:

Scott Grady (rvsg7@rayleehomes.com) (rvsg7@rayleehomes.com)

Subject:

SWPPP inpseciton JTH 3B and Volterra-good

Scott,

Due to the close proximity of JTH 3B and Volterra to the arroyo, I found it prudent to perform a SWPPP inspection.

Both sites area very clean, no trash or other pollutants. Volterra had very little to no sediment in the street. JTH 3B had a little sediment in the street, but I still gave it a pass.

Please keep an eye on it and if we get a decent rainfall that puts sediment in the street, I would appreciate it if you would sweep it.

Thanks, Curtis Cherne, PE Stormwater Quality Engineer 924-3420



From: Sent: Dan Mallak <dmallak@rayleehomes.com> Wednesday, August 10, 2016 11:07 AM

To:

Cherne, Curtis

Subject:

Re: JTH/Volterra SWPPP inspection

Thank you Curtis I sent it to our clean up crew to get done asap

Dan

Sent from my iPhone

- > On Aug 9, 2016, at 1:12 PM, Cherne, Curtis < CCherne@cabq.gov > wrote:
- >
- > Dan.
- > Good afternoon.
- > I hadn't been out to JTH in a while so I figured I'd stop by yesterday.

>

- > It appears that the inlet protection that is in place is functioning, but they are getting full.
- > There was sediment at quite a few of the intersections. I just attached a couple pics. Seems the area is due for a sweepin'.
- > The cement wash-out bin was full and there were numerous wash-outs next to it.
- >
- > Curtis
- > 505-924-3420
- > "Cement (concrete, stucco, mortar...) pollution is preventable.....Let's prevent it. Thank you."
- >
- > <sediment_inlet_protection.jpg>
- > < sediment_street.jpg>
- > <sediment_street2.jpg>
- > <cement_pollution.jpg>



From:

Cherne, Curtis

Sent:

Tuesday, August 09, 2016 1:12 PM

To: Subject: dmallak@rayleehomes.com JTH/Volterra SWPPP inspection

Attachments:

sediment_inlet_protection.jpg; sediment_street.jpg; sediment_street2.jpg;

cement_pollution.jpg

Dan,

Good afternoon.

I hadn't been out to JTH in a while so I figured I'd stop by yesterday.

It appears that the inlet protection that is in place is functioning, but they are getting full.

There was sediment at quite a few of the intersections. I just attached a couple pics. Seems the area is due for a sweepin'.

The cement wash-out bin was full and there were numerous wash-outs next to it.

Curtis

505-924-3420



ECS File: M 22 Ed 1613




City of Albuquerque Stormwater Construction Site Inspection Report

	General Information				
Project Name and Location Two Tabo and Cavalcade					
Site Contact Name & Agency Dan Mallak Pay Lee Hunas Contact Phone # 717-54					
Date of Inspection	6-6-16	Start/End 21/	8/2:30		
Inspector Name, COA Dept.	Curtis Cherne, Sto	ormwater Quality			
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov				
Inspector Qualifications	Qualified Compliance Inspector of Stormwate	r- Stormwater One			
Describe Present Phase of Construction	Streets builty construction	hine			
Type of Inspection:	,				
Regular • During stor	rm event • Post-storm event (> 0.5 inch) • 31	11 / Complaint Respo	onse • Follow-Up		
	Weather Information				
Weather at time of this inspect		-	perature: ~F°		
		Windy			
Amount: • < 1/4" • (4" to	ince the site was Permitted? · Yes · No 4" · > 34" · Snow"				
	Erosion & Sediment Control Inspect	tion			
Entrance / Track-Out	all				
Sediment Controls / Silt Fence, Check Dams, Waddles, etc. Struct in Shut 1 vinus / 5Cashin					
Erosion Controls / Mulch	Erosion Controls / Mulch, Seed, was grand on bunt low Concrete washout pin - grifforen a cavalent - Las				
· Housekeeping/Pollutant Controls Conclude washout per - golfiddian i Caralland - full					
Debris/Pollutants/Sediment in MS4					
• Notes					
Is site being maintained in complian		Cint o C	Date		

SC Inspection Form (Rev April2016).docx

Rutan phopies



From:

Cherne, Curtis

Sent:

Wednesday, May 04, 2016 11:39 AM

To:

'TSnolan@drhorton.com' tim@superiorstormwater.com

Cc: Subject:

Volterra Villas SWPPP inspection

Attachments:

grass.jpg; nice_wattle.jpg; cement_pollution1.jpg; cement_pollution2.jpg; oil_street.jpg

Tim Nolan,

Good morning.

I stopped by your office yesterday around 3 to go over this stuff, but the door was locked.

I am not sure if Volterra Villas is yours or not, but you are just up the hill and work for the same builder. Please let me know if I should send this to someone else.


I noticed grass growing on one of the lots. That's great! How did you get that to happen? I really like the wattle. Is that one of DR Horton's or did Superior come up with that one? The streets were relatively clean. Thanks.

However, I did find the following issues at the site:

- 1. Cement pollution on two lots. I started an outreach program last week to address this and I welcome any suggestions.
- 2. One piece of equipment is leaking oil on the street. Probably needs maintenance.

Curtis

505-924-3420




ECS File: MY Enloy



	General Informatio	n			
<u>.</u>					
Project Name and Location	Munachas Ltvins	ESC PERMIT #			
Site Contact Name & Agency	Or. Hurton Brent Cesty 10-21-15	Contact Phone # SOS - 797 - 433			
Date of Inspection /b-21-15 Start/End /2 SJ /2:2					
Inspector Name, COA Dept.	Curtis Che	rne, Stormwater Quality			
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov				
Inspector Qualifications	Stormwater USA WC				
Describe Present Phase of Construction Type of Inspection:		on Sorven			
Regular · Drive-By/R	andom • During storm event • P	ost-storm event • 311 / Complaint Response			
	Weather Information	on			
, (Rain · Sleet · Fog · Snowing ince the site was Permitted? · Yes	- High Winds - Other:			
Amount. (A)	Erosion & Sediment Control				
 Check any BMPs that have Entrance / Off Tracking Sediment Controls / Silt In Check Dams, Waddles Erosion Controls / Mulch Wind Blown Erosion Housekeeping / Pollutant 	, sec. <u>OK</u> , Seed, <u>NO</u>	ANCE			
Is site being maintained in complia	ance with Const. Gen. Permit ? * (Yes) * No	Signature Date			

59				
			et.	




jar :

Dan Malike - in chan of same program Raley hopes JT4 313 Viden Call his book Wishe - Spreed-out Pales -Loner mark and swells by to be prouv I marial e roy la hour com

marial e roy

ma 1. complex 2. premme or herges






Te						
	General Information					
Project Name and Location	Notables and Times Army	ESC PERMIT #	~0			
Site Contact Name & Agency	OR- Hardon Brut Lesley	Contact Phone #	505-797-4245			
Date of Inspection	7-21-15	Start/End Time 10:	10/10:20			
Inspector Name, COA Dept.	Curtis Cherne, Sto	ormwater Quality				
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov					
Inspector Qualifications	Stormwater USA	10				
Describe Present Phase of Construction	regrading previously grades	Jods for	fruits back			
 Type of Inspection: Regular Prive-By/R Follow-Up 						
	Weather Information					
Weather at time of this inspect	Rain · Sleet · Fog · Snowing ·		perature: ~15 F°			
Has there been a storm event s Amount: • < 1/4" (1/4") to 3	ince the site was Permitted? · les · No 4" · > 34" Intensity: · Light · Me	ed. • Hvy.	• Snow"			
	Erosion & Sediment Control Inspec	tion				
Check any BMPs that h	ave FAILED or REQUIRE MAINTENANCE					
Entrance / Off Tracking	NO					
Sediment Controls / Silt Fence, Check Dams, Waddles, etc.						
Erosion Controls / Mulch, Seed,						
• Wind Blown Erosion						
* Housekeeping / Poliutant Controls						
Is site being maintained in complia	ance with Const. Gen. Permit ?" Yes " No Si	ignature	7-21-1 Date			

NPDES	Tracking	No:
THE DESCRIPTION	ILACMINE	110.

ECS File: <u>A 22 E0168</u>



		Information				
Project Name and Location	Juan Tabo Bus	3.0	ESC PERMIT #			
Site Contact Name & Agency			Contact Phone #			
Date of Inspection	6-10-15		Start/End G:A	9100/9:11		
Inspector Name, COA Dept.		Curtis Cherne, St	ormwater Quality			
Inspector Phone / E-mail	505-924-3420/ccherne@cab	q.gov				
Inspector Qualifications	Stormwater USA					
Describe Present Phase of Construction	Lots grades,	strutt bi	unt			
Type of Inspection:	•					
 Regular Drive-By/R 	andom • During storm eve	ent • Post-stori	m event • 311/0	Complaint Response		
• Follow-Up						
	Weather 1	Information				
Weather at time of this inspects lear · Cloudy · I	ion? Rain · Sleet · Fog ·	Snowing • 1		perature: ~ 75 F°		
Has there been a storm event si Amount: • < 1/4" • 1/4" to 3			d. • H vy.	• Snow"		
	Erosion & Sedimer	nt Control Inspec	tion			
Check any BMPs that ha	ave FAILED or REQUIRE M	IAINTENANCE				
• Entrance / Off Tracking	NP	<u> </u>				
• Sediment Controls / Silt Fence, Check Dams, Waddles, etc.						
Erosion Controls / Mulch, Seed,						
• Wind Blown Erosion						
Housekeeping / Pollutant	Controls Good					
· Little to NO. S	· Little to no Stant in Squet, No drush or political					
Is site being maintained in complian	nce with Const. Gen. Permit ?		ent ch	G-11-11 Date		



From:

Patrick B Lesley <PBLesley@drhorton.com>

Sent:

Monday, May 08, 2017 5:03 PM

To:

Cherne, Curtis

Subject:

RE: trash at volterra villas and stormcloud

Thanks, Curtis. I forwarded your email to the guy last week that was supposed to oversee the cleanup. I followed up with a phone message and email to his boss this afternoon. I told him I'd meet his crew on site as soon as possible to direct the further cleanup, meaning this week.

Appreciate it. I'll take before-and-after pics.

-Brent

From: Cherne, Curtis [mailto:CCherne@cabq.gov]

Sent: Wednesday, May 3, 2017 3:02 PM

To: Patrick B Lesley < PBLesley@drhorton.com > Subject: trash at volterra villas and stormcloud

Brent,

Good afternoon.

I went out to Volterra Villas today for a follow-up inspection after receiving your e-mail that you had a crew to address the blow trash and construction debris. It maybe looked a little better and I know we discussed that you didn't have to get all of it, but how much did they get?

I didn't get photos of the beer cans and broken bottles. Those could have been from "visitors". The sheetrock on the side of the scour wall is most likely from DR Horton construction activity. There is lots of other stuff too.

I guess I expected to only see 10 to 20% of the trash not 75%.

I was continuing my west side inspections, so figured I'd stop in at Stormcloud as DR Horton and Raylee are both in there. Lots of trash on Warm Wind street (DR Horton). Pics will be sent in separate e-mail. Please drive your site, then go around the corner (Raylee) and see the difference.

Curtis Cherne, PE, QCIS Principal Engineer Stormwater Quality COA 505-924-3420



ECS File: 11:22 50168



	General Information					
Project Name and Location	Monachos L Juan Tabo					
Site Contact Name & Agency	John Godin Contact Phone #/ Ee &C E-mail					
Date of Inspection 6-8-17 Start/End 7:30 / 1:4						
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality					
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov					
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One					
Describe Present Phase of Construction	AM units wheat					
Type of Inspection: Regular During store						
	Weather Information					
	Rain · Sleet · Fog · Snowing · Windy					
Has there been a storm event s Amount: • < 1/4" • 1/4" to 3	nce the site was Permitted? · Yes) · No 4" · > 34" · Snow"					
	Erosion & Sediment Control Inspection					
Entrance / Track-Out _	NIA- of no treck-out					
Sediment Controls / Silt F Check Dams, Waddles	· • • • • • • • • • • • • • • • • • • •					
Erosion Controls / Mulch	Erosion Controls / Mulch, Seed, 3 ravel					
* Housekeeping/Pollutant Controls						
Debris/Pollutants/Sedime	Debris/Pollutants/Sediment in MS4					
Notes						
Is site being maintained in complian	ace with the Drainage Ordinance? (Yes) No Cut a chu 6-8-17 Signature Date					

ECS File: MPA EU1612



General Information		
Project Name and Location	Voltura VILLAS	
	Nothern VIllas Munachos & Juan Vabu Brus Lesley Contact Phone #/	
Site Contact Name & Agency	Brus Lesley Dr Worken	E-mail
Date of Inspection	5-3-17	Start/End 9! OU 9:20
Inspector Name, COA Dept.	Curtis Cherne, Sto	,
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov	
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One	
Describe Present Phase of Construction Most Unit built		
Type of Inspection:		
- Regular • During storm event • Post-storm event (> 0.5 inch) • 311 / Complaint Response • Follow-Up		
Weather Information		
Weather at time of this inspection? Clear · Cloudy · Rain · Sleet · Fog · Snowing · Windy Temperature: F°		
Has there been a storm event since the site was Permitted? · Yes · No Amount: · < 1/4" · 1/2" to 1/4" · > 3/4" · Snow"		
Erosion & Sediment Control Inspection		
 Entrance / Track-Out Sediment Controls / Silt Fence, Check Dams, Waddles, etc. Erosion Controls / Mulch, Seed, Housekeeping/Pollutant Controls Debris/Pollutants/Sediment in MS4 Notes		
Is site being maintained in compliance with the Drainage Ordinance? Yes No Signature Date		



From:

Cherne, Curtis

Sent:

Wednesday, May 03, 2017 3:02 PM

To:

pblesley@drhorton.com

Subject:

trash at volterra villas and stormcloud

Attachments:

trash2.jpg; White_wrapper_gypsumxxx.jpg; sheetrock.jpg; trash.jpg

Brent,

Good afternoon.

I went out to Volterra Villas today for a follow-up inspection after receiving your e-mail that you had a crew to address the blow trash and construction debris. It maybe looked a little better and I know we discussed that you didn't have to get all of it, but how much did they get?

I didn't get photos of the beer cans and broken bottles. Those could have been from "visitors". The sheetrock on the side of the scour wall is most likely from DR Horton construction activity. There is lots of other stuff too.

I guess I expected to only see 10 to 20% of the trash not 75%.

I was continuing my west side inspections, so figured I'd stop in at Stormcloud as DR Horton and Raylee are both in there. Lots of trash on Warm Wind street (DR Horton). Pics will be sent in separate e-mail. Please drive your site, then go around the corner (Raylee) and see the difference.

Curtis Cherne, PE, QCIS Principal Engineer Stormwater Quality COA 505-924-3420

From:

Patrick B Lesley <PBLesley@drhorton.com>

Sent:

Tuesday, May 02, 2017 4:13 PM

To: Cc: Cherne, Curtis Lou G Gibney

Subject:

RE: Volterra VIIIas Violation Letter

Hello Curtis-

Circling back to let you know we had a crew on site on April 19th to address the blow trash and construction debris associated with our construction.

Thanks. Feel free to call anytime.

-Brent 505-991-3610

From: Cherne, Curtis [mailto:CCherne@cabq.gov]

Sent: Wednesday, April 5, 2017 2:35 PM

To: Patrick B Lesley < PBLesley@drhorton.com > Subject: RE: Volterra VIIIas Violation Letter

Yes.

From: Patrick B Lesley [mailto:PBLesley@drhorton.com]

Sent: Wednesday, April 05, 2017 11:08 AM

To: Cherne, Curtis

Cc: Lou G Gibney; Grant Morrison

Subject: RE: Volterra VIllas Violation Letter

Thanks, Curtis. Do you have a copy of the letter you can forward?

Appreciate it.

-Brent

From: Cherne, Curtis [mailto:CCherne@cabq.gov]

Sent: Wednesday, April 5, 2017 10:45 AM

To: Patrick B Lesley < PBLesley@drhorton.com >
Cc: Lou G Gibney < lggibney@drhorton.com >
Subject: Volterra VIllas Violation Letter

Brent,

I called yesterday to discuss and left voicemail.

Please see letter.

Curtis Cherne, PE, QCIS

Principal Engineer Stormwater Quality COA 505-924-3420



City of Albuquerque Stormwater Construction Site Inspection Report

	General Information				
Project Name	Volture VIVa				
and Location	meraches and Oran Arts				
Site Contact Name & Agency	Brut lesley Contact Phone #/ E-mail				
	OP Horton Start/End /				
Date of Inspection	4-4-17 Start/End 12:24 12:50				
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality				
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov				
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One				
Describe Present Phase of Construction	Constructio Love 85% complete				
Type of Inspection: Regular During store	rm event • Post-storm event (> 0.5 inch) • 311 / Complaint Response • Follow-Up				
-	Weather Information				
Weather at time of this inspection? • Clear Gloudy • Rain • Sleet • Fog • Snowing • Windy Temperature: ~					
	ince the site was Permitted? · Yes · No				
Amount: • < ¼" • ¼" to 3					
	Erosion & Sediment Control Inspection				
Entrance / Track-Out _	N/A				
Sediment Controls / Silt Fence, New Inlet protection in Morally Check Dams, Waddles, etc.					
• Erosion Controls / Mulch, Seed, (drash in Arryo					
* Housekeeping/Pollutant Controls					
Debris/Pollutants/Sediment in MS4					
• Notes W ~SS					
Is site being maintained in compliance with the Drainage Ordinance? Yes (No Signature Date					



anus that I couse the down to Brook Why -

	Check boxes if plans/permit are approved:	=	k boxes if plans/permit are approved:
		Croding Plan	
ck boxes if plans/permit are approved:	The Figure 1 of Frading Plan		FSC Plan Grading Plan

Cherne, Curtis

From:

Cherne, Curtis

Sent:

Wednesday, April 05, 2017 10:45 AM pblesley@drhorton.com
'Lou G Gibney'

To: Cc:

Subject:

Volterra VIIIas Violation Letter

Brent,

I called yesterday to discuss and left voicemail.

Please see letter.

505-924-3420

Curtis Cherne, PE, QCIS **Principal Engineer Stormwater Quality** COA

"Cement (concrete, stucco, mortar...) pollution is preventable.....Let's prevent it. Thank you."

B)

April 5, 2017

Brent Lesley, DRH Southwest Construction: pblesley@drhorton.com

Volterra Villas: Juan tabo and Monachos

Copy: Lout Gibney, DR Horton: lggibney@drhorton.com

Re: Drainage Ordinance (14-5-2-1) Violation for Trash in Arroyo

Dear Mr. Lesley,

On March 9th, 2017, Stormwater Quality requested that you remove trash from the Tijeras Arroyo.

At yesterday's inspection, trash is still present in the arroyo. In addition, a considerable amount of trash has blown west of your project as shown in the photos below.


Photos are shown below:

PO Box 1293

Albuquerque

New Mexico 87103





PO Box 1293

Albuquerque

New Mexico 87103



	=2.78	0-1-		
				*



PO Box 1293

Albuquerque

New Mexico 87103





PO Box 1293

Albuquerque

New Mexico 87103



23

-



Required mitigation:

1. Remove trash.

If the violation is not mitigated within 30 days, the property owner is subject to a fine of \$500/day per the City's Drainage Control Ordinance.

If you would like to schedule a follow-up inspection at a day and time of your convenience, prior to 30 days from the date of this letter please let me know.

If you have any questions, you can contact me at 924-3420.

Sincerely, Cent c Chem

Curtis Cherne, P.E.

Principal Engineer, Stormwater Quality

Planning Dept.

PO Box 1293

Albuquerque

New Mexico 87103



City of Albuquerque

Planning Department

Stormwater	Control	Permit fo	r Erosion	and	Sediment	Control

Project Title Juan Tabo Hills Unit 3B / Voltura VIllasa
Project Location (Major Cross Streets/Arroyo or address)
Juan Tabo Blvd./Monachos
Property Owner: (or authorized agent provided in writing)
eNOI Number: NMR15FJ70 ^{Cc} NMR19 8901 cc
Attach 2012 Construction General Permit eNOI Detail sheet.
Property Owner: <u>DRH Southwest Construction</u>
Site Contact Name Brent Lesley
Site Contact Phone 505-798-7655
Site Contact e-mail_PBLesley@drhorton.com
Applicant: Print Name Elaine Aragon Date 8/22/16
For City personnel use only:
Check boxes if plans/permit are approved:
ESC Plan Grading Plan Flood Plain-Permit (strike if not required)
The Project is approved for grading (enter date): 8-5-15
City Personnel Printed Name: Curtis Cherne
(Rev January 2016)



Cherne, Curtis

From: Sent: Elaine B Aragon <EBAragon@drhorton.com> Wednesday, September 14, 2016 6:50 AM

To: Subject: Cherne, Curtis RE: New ESC Form

Oops. Volterra Villas is NM12B901.

Elaine Aragon

Assist. to Operation Manager

DR Horton-Albuquerque

Phone: 505-798-7645 Fax: 505-797-9881 EFax: 1-817-928-2062



From: Cherne, Curtis [mailto:CCherne@cabq.gov]
Sent: Tuesday, September 13, 2016 3:54 PM

To: Elaine B Aragon
Subject: RE: New ESC Form

Elaine,

I'm not getting any hits on the eNOI number you provided; NMR15FJ70. I also tried NMR12FJ70 (most ABQ are NMR12) and did a "rough" search on Juan Tabo Hills to no avail.

Please check eNOI number.

Curtis

From: Elaine B Aragon [mailto:EBAragon@drhorton.com]

Sent: Tuesday, September 13, 2016 1:50 PM

To: Cherne, Curtis Subject: New ESC Form

Hello. Here is a new ESC Form ready for your approval.

Thanks.

Elaine Aragon Assist. to Operation Manager DR Horton-Albuquerque Phone: 505-798-7645

Fax: 505-797-9881 EFax: 1-817-928-2062





You are here: Permits Landing Page 2012 CGP 2012 CGP Details

2012 Construction General Permit eNOI Detail

Quick J

Details for NMR12B901

General Information

Project / Site Name: Current Status:

Tracking Number:

Permit Type:

Volterra Villas

Active

NMR12B901

NOI

Interview Page Answers

Is your project/site located in Indian Country Lands?

Are you requesting coverage under this NOI as a 'federal operator' as

defined in Appendix A?

Νo

No

Operator Information

Operator's Name:

Street:

City:

Zip Code:

Point of Contact Name:

Phone Number:

Operator Email:

Fax:

IRS Employer Identification Number (EIN):

D.R. Horton Inc

4400 Alameda NE Suite B

Albuquerque

New Mexico

87113

Brent Lesley

(505) 797-4245

pblesley@drhorton.com

N/A

N/A

Project / Facility Information

Project / Site Name:

Street:

City:

State:

Zip Code:

Project / Facility on Indian Land?

Volterra Villas

N/A

Albuquerque

New Mexico

87116

No

Reservation Name:

N/A

Additional Project Information

Is your project an 'emergency-related project' as defined in Appendix

Have stormwater discharges from your project/site been covered

previously under an NPDES permit?

Estimated Project Start Date:

Estimated Project End Date Have earth-disturbing activities commenced on your project/site?

County or Similar government subdivision:

No

07/30/2015

07/30/2016

No

Bernalillo

Latitude and Longitude Information

106.5155 Longitude:

Longitude Unit: (degrees, decimals)

Latitude: 35.0543

Latitude Unit: (degrees, decimals)

Latitude / Longitude Data Source: Google Earth Horizontal Reference Datum Unknown

Estimated Area to be Disturbed (to the nearest quarter acre):

Chemical Treatment Information

Will you use polymers, flocculants, or other treatment chemicals at your construction site?

No

ESA

Under which criterion listed in Appendix D are you eligible for coverage under this permit?

C. Federally-listed threatened or endangered species or designated critical habitat(s) are likely to occur in or nea site's "action area," and your site's discharges and disch related activities are not likely to adversely affect listed threatened or endangered species or critical habitat. Thi determination may include consideration of any stormw controls and/or management practices you will adopt to that your discharges and discharge-related activities are likely to adversely affect listed species and critical habitmake this certification, you must include the following i NOI: 1) any federally listed species and/or designated his located in your "action area"; and 2) the distance betwee site and the listed species or designated critical habitat You must also include a copy of your site map with your NMED Website and USFWS Website

Provide the basis for criterion selection selected:

 Any federal listed species and/or designated habitat located in your Rio Grande River area:



2) The distance between your site and the listed species or designated ~ 11.1 Miles critical habitat (in miles):

SWPPP Point of Contact

Name:

Organization Name:

Phone: Fax:

Email:

Brent Lesley D.R. Horton Inc (505) 797-4245

No

N/A

pblesley@drhorton.com

Discharge Information

Does your project/site discharge stormwater into a Municipal Separate $_{\mbox{Yes}}$

Storm Sewer System (MS4)?

Are there any surface waters within 50 feet of your project's earth

disturbances?

If a TMDL has been approved or established, identify the title or

reference of the TMDL document:

Impaired Surface Waters to Which you Discharge

Surface water(s) to which you discharge	Impaired Water	Listed Water Pollutant(s)	Tier 2, 2.5 or 3	Source	TMI
Tijeras Arroyo	No		No	NMED Website	
Rio Grande River	Yes	FISH CONSUMPTION ADV	Yes	NMED Website	EC

Historic Preservation

Is your project/site located on a property of religious or cultural

significance to an Indian tribe?

If yes, provide the name of the Indian tribe associated with the property:

Are you installing any stormwater controls as described in Appendix E that require? (Appendix E, Step 1):

If yes, have prior surveys or evaluations conducted on the site have already determined historic properties do not exist, or that prior disturbances have precluded the existence of historic properties? (Appendix E, Step 2):

If no, have you determined that your installation of subsurface earthdisturbing stormwater controls will have no effect on historic properties? (Appendix E, Step 3):

If no, did the SHPO, THPO, or other tribal representative (whichever applies) respond to you within the 15 calendar days to indicate whether the subsurface earth disturbances caused by the installation of stormwater controls affect historic properties? (Appendix E, Step 4)

N/A

No

Yes

N/A



Certifier Information

Name:

Title:

Email:

Certified Date:

Bradley kile

N/A

brkile@drhorton.com

07/21/2015

Preparer Information

Name:

Phone:

Fax:

Organization:

Email:

Tim Slatunas (505) 353-2558

N/A

SUPERIOR STORMWATER SERVICES LLC

tim@superiorstormwater.com

Corresponding Documents

File Name

File Size

File Section

Date Uploaded

BMP Plan Volterra Villas.pdf

4585296

ESA Section

21-JUL-15

Back to Search Results

Fi Printer Friendly

release 1.4



Cherne, Curtis

From:

Cherne, Curtis

Sent:

Thursday, March 09, 2017 10:29 AM

To:

pblesley@drhorton.com

Subject: Attachments: Volterra Villas SWPPP inspection trash_arroyo.jpg; trash_arroyo2.jpg

Brent,

Good morning.

I was out at Volterra Villas yesterday for an inspection.

The site looked good except for the trash in the arroyo at the base of the scour wall. Please remove trash.

Curtis Cherne, PE, QCIS Principal Engineer Stormwater Quality COA

505-924-3420

[&]quot;Cement (concrete, stucco, mortar...) pollution is preventable.....Let's prevent it. Thank you."



ECS File: MDD EU1613



City of Albuquerque Stormwater Construction Site Inspection Report

	General Information		
Project Name and Location	Voltore Mas		
Site Contact Name & Agency	Con Gibres - FUM Figh Brut Lisky	Contact Phone #/ E-mail	PBCosky el dehorpe. con
Date of Inspection	3-8-17	Start/End //	135/11:50
Inspector Name, COA Dept.	Curtis Cherne	, Stormwater Quality	
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov		
Inspector Qualifications	Qualified Compliance Inspector of Storm	water- Stormwater One	
Describe Present Phase of Construction	3 houses bunt		
Type of Inspection: Regular • During stor	rm event • Post-storm event (> 0.5 inch)	• 311 / Complaint Resp	onse · Follow-Up
	Weather Information	1	
Weather at time of this inspect Clear · Cloudy · I Has there been a storm event s Amount: · < ¼" · ¼" (q)	Rain · Sleet · Fog · Snowing ince the site was Permitted? · (es) · No	• Windy	perature: ~_66F°
Amount: • < 1/4" • 1/4" to)	*** · > *4" · Show Erosion & Sediment Control Ins	spection	
Entrance / Track-Out Sediment Controls / Silt I	ok Fence, ok		
Check Dams, Waddles Erosion Controls / Mulch Housekeeping/Pollutant C	s, Seed, gravel frash in Arrayo		
Debris/Pollutants/Sedime	ent in MS4 Yer, Some drag	rk	
Notes			
Is site being maintained in complian	nce with the Drainage Ordinance ? • Yes • No	Cut a Chi	3-8-17 Date

