# Heritage Trails Dev: Aspire Subdivision Units 2-4



### **Storm Water Compliance Inspection Form**

PO Box 400 Los Lunas, NM 87042 www.greenglobenm.com

Inspection Type: Routine Date: 10-07-2021 Time: 2:37 PM

Permit Tracking #: NMR1003RV Inspector Name: Lorenzo Santistevan Qualifications: Compliance Inspector

Current Weather Conditions: Date and Amount of Last Recordable Storm Event: 07-27-2021 .50

#### **Construction Time Line:**

Action	Start Date	Date Complete
Initial BMP Installation	05-27-2021	
Clearing and Grubbing	07-22-2021	
Utility Installation		
Construction of Structure		
Final Stabilization		

#### Site Walk

Olto Maini				
Question	Yes	No	N/A	Comment
Is there a proper posting sign?	$\boxtimes$			
Are areas that have been disturbed, but not under construction been properly stabilized?				
Velocity Reduction Devices i.e. Check Dams, Berms, Etc.				
Silt Fence	$\boxtimes$			
Wattles/Filter Sock			$\boxtimes$	
Inlet Protection			$\boxtimes$	
Cut Back Curbs			$\boxtimes$	
Waste Management			$\boxtimes$	
Vehicle Tracking Control	X			
Material Storage			$\boxtimes$	
Dust Control	X			
Street Sweeping	X			
Construction Washouts i.e. Concrete, Paint, Stucco Etc.				
Discharge Points			$\boxtimes$	
Sanitary Stations	$\boxtimes$			
Stockpiles	$\boxtimes$			
Other			$\boxtimes$	

### **Heritage Trails**

# Heritage Trails Dev: Aspire Subdivision Units 2-4

**NMR1003RV** 

Date

Date

10-07-2021

### **SWPPP Information:**

Question	Yes	No	N/A	Comment
Is the SWPPP kept on site?	$\boxtimes$			
Was the SWPPP updated at the time of the inspection?				
Are all certification pages signed?	$\boxtimes$			
Are inspector qualifications in the SWPPP?	$\boxtimes$			
Is there a copy of the NOI and Acknowledgement letter?				
Is there a delegation letter in the SWPPP?	$\boxtimes$			
Was the last inspection/CAL certified?	$\boxtimes$			
personnel properly gathered and evaluated the information subm	nitted. Base e best of n	ed on my i ny knowled	nquiry of tl dge and be	direction or supervision in accordance with a system designed to assure that qualifier ne person or persons who manage the system, or those persons directly responsible lief, true, accurate, and complete. I am aware that there are significant penalties for tions."

Name
Additional Comments:

Operator: Rico Gallegos

Owner: Garret Price
Name

Signature

Signature

Low Hollya

## Heritage Trails Dev: Aspire Subdivision Units 2-4



**Action Log:** 

	Location	Action Type	Action Required	Date Noted	Date Completed	Initials
--	----------	-------------	-----------------	------------	-------------------	----------

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Inspector: Lorenzo Santistevan

10-07-2021

Name Signature

Date





6/9/21





6-24-21



8/12/21