

City of Albuquerque Stormwater Construction Site Inspection Report

General Information						
Project Name:	Los Diamantes					
Location:	98th Street & Gibson					
Site Contact Name &	Kevin Griffin		ESC File No.	N09E013		
Agency	DR Horton		NPDES Id. No.		NMR12BN02	
Inspection Date:	02/22/19	Start/End Time:	1000/1030hrs			
CoA Stormwater Inspector:		Timothy Sims, Stormwater Inspector				
Present Phase of	home construction					
Construction:						
Type of Inspection: x	Regular	Storm Event	Post Storm I	Event >0.25"	311/Complaint	Follow Up
Weather at time of inspection?			Temperature: ~ 48*		48*	
clear/Windy				_		
Has there been a storm event since site was Permitted?						
Clarify amount: (i.e <1/4" to >3/4"):		yes	, >3/4"			

Inspection

CGP Section	BMP / Activity	Maintenance or Corrective Action Required	Location and Notes
1.5	Post a Notice		
2.2.1	Provide and maintain Natural buffer when Waters of the US <50ft.		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.4	Minimize sediment track out		

2.2.5	Manage stock piles			
2.2.6	minimize dust			
2.2.10	Protect storm drain inlets			
2.2.10	Protect storm drain inlets			
2.2.11	Minimize erosion of conveyance channels			
2.2.12	Sediment Basins			
2.2.14	Stabilize exposed portions of the site			
2.2.14	Stabilize exposed portions of the site			
2.2.14	Stabilize exposed portions of the site			
2.2.14	Stabilize exposed portions of the site			
2.3.1	Equipment and vehicle fueling			
2.3.2	Equipment and vehicle washing			
2.3.3	Building material storage			
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage			
2.3.3	Construction and domestic wastes			
2.3.3	Construction and domestic wastes			
2.3.4	Washing applicators used for paint, stucco, concrete, etc.			
2.3.4	Washing applicators used for paint, stucco, concrete, etc.			
2.3.4	Washing applicators used for paint, stucco, concrete, etc.			
2.4	Dewatering			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports	requested	Latest report Date:	
Notes: (City Inspector Use) Items in compliance can be left blank.				
1	Construction Congral Pormit (CG)	D)		

Maintenance or corrective actions are to be completed within seven (7) days.

Notes:			
Please for	orward me the latest self-inspection report		
	_	<u> </u>	

City of Albuquerque S		
Contact information:	Timothy Sims, 505-803-6155 or	02/22/19

tsims@cabq.gov

Construction General Permit (CGP)