City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Los Diamantes						
Location:	98th & Cochise ln sw						
Site Contact Name & Agency	Kevin Griffin- DRHorton			ESC File No.	N09E013		
	ktgriffin@drhorton.com			NPDES Id. No.	NMR12BN02		
Inspection Date:	06/16/20	Start/End Time:	0845/0900hrs				
CoA Stormwater Inspector:	Timothy E. Sims						
Construction Phase:	STABILIZED						
Type of Inspection:	x Regular	Storm Event		Post Storm Event >0.25"		311/Complaint	Follow Up

Weather at time of inspection?	Clear	Temperature: ~	71*
Estimated date of last storm 0.25" or greater		6/1/2020	

Item Number	Deficiency/ Corrective Action			
	STABILIZED			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports		Latest report Date:	

Notes:	

City of Albuquerque Stormwater Inspector Signature and date: Timothy E. Sims

Digitally signed by Timothy E. Sims
DN: cn=Timothy E. Sims, o=Stormwater Inspectionos, ou=Planning, email=tsims@cabq.gov, c=US
Date: 2020.06.18 08:00:04 -06'00'

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov 06/16/20