



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Los Diamantes				
Location:	98th & Cochise In sw				
Site Contact Name & Agency	Kevin Griffin- DRHorton	ESC File No.	N09E013		
	ktgriffin@drhorton.com	NPDES Id. No.	NMR12BN02		
Inspection Date:	06/18/19	Start/End Time:	1300/1320hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	Home construction				
Type of Inspection:	<input checked="" type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input type="checkbox"/> 311/Complaint	<input type="checkbox"/> Follow Up

Weather at time of inspection?	Clear	Temperature: ~	86*
Estimated date of last storm 0.25" or greater	5/11/2019		

Item Number	Deficiency/ Corrective Action		
1	please provide me the latest SWPPP self-inspection report		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	requested	Latest report Date: 4/18/2019

Notes:	site has domestic waste on vacant lots. (it appears to be local residential waste).
	please clean as needed.

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 06/18/19