



# City of Albuquerque Stormwater Construction Site Inspection Report

## General Information

Project Name:	Desert Sands				
Location:	Colobel & Gison				
Site Contact Name & Agency	Dale Works	ESC File No.	N09E014		
	LGI Homes	NPDES Id. No.	NMR12BP74		
Inspection Date:	04/18/19	Start/End Time:	0840/0900hrs		
CoA Stormwater Inspector:	Timothy Sims, Stormwater Inspector				
Construction Phase:	home construction				
Type of Inspection:	Regular	Storm Event	x	Post Storm Event >0.25"	311/Complaint
					Follow Up

Weather at time of inspection?	Clear	Temperature: ~	47*
Has there been a storm event since site was Permitted?			
Clarify amount: ( i.e.. <1/4" to >3/4"): yes, >1/4"			

Item Number	Deficiency/ Corrective Action		
1	provide self inspection report. >0.25" rainfall on 04/17/19		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	requested	Latest report Date:

Notes: (City Inspector Use) Items in compliance can be left blank.

<sup>1</sup> Construction General Permit (CGP)

Maintenance or corrective actions are to be completed within seven (7) days.

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:  
Contact information: Timothy Sims, 505-803-6155 or  
[tsims@cabq.gov](mailto:tsims@cabq.gov)

04/18/19