

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
Project Name:		Desert Sands					
Location:		Colobel & Gison					
Site Contact Name & Agency		Dale Works		ESC File No.	N09E014		
		LGI Homes		NPDES Id. No.	NMR12BP74		
Inspection Date:		04/18/19	Start/End Time:	0840/0900hrs			
CoA Stormwater Inspector:			Timothy Sims, Stormwater Inspector				
Construction Phase:		home construction					
Type of Inspection:		Regular	Storm Event	x	Post Storm Event >0.25"	311/Complaint	Follow Up

Weather at time of inspection?	Clear	Temperature: ~	47*
Has there been a storm event since site was Permitted?			
Clarify amount: (i.e.. <1/4" to >3/4"):	yes, >1/4"		

Item Number	Deficiency/ Corrective Action		
1	provide self inspection report. >0.25" rainfall on 04/17/19		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	requested	Latest report Date:

Notes: (City Inspector Use) Items in compliance can be left blank.

1 Construction General Permit (CGP)

Maintenance or corrective actions are to be completed within seven (7) days.

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy Sims, 505-803-6155 or
tsims@cabq.gov

04/18/19