

## City of Albuquerque Stormwater Construction Site Inspection Report

## General Information

Project Name:		Desert Sands					
Location:		Colobel & Gibson					
Site Contact Name & Agency	Dale Works - LGI homes			ESC File No.	N09E014		
	dale.works@lgihomes.com			NPDES Id. No.	NMR12BP74		
Inspection Date:	06/18/19	Start/End Time:	1320/1415hrs				
CoA Stormwater Inspector:		Timothy E. Sims					
Construction Phase:		home construction					
Type of Inspection:	X	Regular	Storm Event	Post Storm Event >0.25"	311/Complaint	Follow Up	

Weather at time of inspection?	Clear	Temperature: ~	91*
Estimated date of last storm 0.25" or greater	5/11/2019		

Item Number	Deficiency/ Corrective Action			
1	Please provide me the latest SWPPP self-inspection report.			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports	requested	Latest report Date:	4/18/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:  
Contact information: Timothy E. Sims - (505) 803-6155  
[tsims@cabq.gov](mailto:tsims@cabq.gov) 06/18/19