City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Desert Sands		
Location:	Colobel & Gibson		
Site Contact Name & Agency	Dale Works - LGI homes	ESC File No.	N09E014
	dale.works@lgihomes.com	NPDES Id. No.	NMR12BP74
Inspection Date:	07/19/19	Start/End Time:	0940/1000hrs
CoA Stormwater Inspector:	Timothy E. Sims		
Construction Phase:	home construction		

Type of Inspection:	X	Regular		Storm Event		Post Storm Event >0.25"		311/Complaint		Follow Up

Weather at time of inspection?	Clear	Temperature: ~	79*
Estimated date of last storm 0.25" or greater		7/7/2019	

Item Number	Deficiency/ Corrective Action			
1	Please provide me the latest SWPPP self-inspection report.			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports	requested	Latest report Date:	6/19/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date: Timothy E. Sims 07/19/19

Digitally signed by Timothy E. Sims
DN: cn=Timothy E. Sims, o=Stormwater Inspectionos, ou=Planning, email=tsims@cabq.gov, c=US
Date: 2019.07.19 09:54:56 -06'00'

Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov