

City of Albuquerque Stormwater Construction Site Inspection Report

General information								
Project Name:		Desert Sands						
Location:		Colobel & Gib	son					
Site Contact Name &		Mark Kaberlir	n - LGI homes	ESC File No.		N09E014		
Agency		mark.kamberl	in@lgihomes.com	NPDES Id. No.		NMR12BP74		
Inspection			tart/End Time: 08				•	
	water Inspecto		imothy E. Sims					
	ction Phase:		,	home co	nstruction			
Type of Inspection:		Regular	Storm Event	Post Storm I		311/Complaint x	Follow Up	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		riegulai	0.0			(σ22) σστιριατική χ	renew ep	
Weather at time of inspection? Clear Temperature: ~ 79*								
Estimated	date of last s	torm 0.25" o	r greater	• •	rempe	7/7/2019	, 3	
	Grante or restro		. <u>A. Garto</u> .			77772013		
Item			Deficienc	v/ Correctiv	e Action			
Number	Deficiency/ Corrective Action							
	all previous issues resolved, no new issuese observed with this inspection.							
	an previous issues resolved, no new issuese observed with this hispection.							
2.1	Discharge off site?	(Y/N)	No					
4		tion Poports		Latest rer	ort Date:	9/6/201	0	
4	Sell Hispeci	tion Reports		Latest rep	oort Date:	9/0/201	9	
Notes:								

 ${\bf City\ of\ Albuquerque\ Stormwater\ Inspector\ Signature\ and\ date:}$

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

09/13/19_____