

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information										
ESC File No.	N09E	014 Project Name:			Desert Sands					
NPDES Id. No.	NMR1000BE		Location:		3000 98th St SW					
1/2	1/27/2021		Owner			Contractor				
Operator		LGI Homes								
Contact name & title		Eddie Loven								
e-mail		Eloven@lgihomes.com								
Contact Phone #		872-1700								
COA Inspector		Doug Hughes			Start/End Time	: 4:30pm				
Construction Phase:					ure complete					
Type of Ir	nspection:	Regular	Storm Event	Post Storm	Event >0.25"	311/Complaint Follow Up				
Weath	er at time of i	inspection?	Clea	ar	Tempe	rature: ~ 70				
Estimated	date of last	storm 0.25"	or greater			2/22/2021				
	Deficiency/ Corrective Action									
Number										
1	The NPDES coverage needs posted near the north pond. The SWPPP location must also be identified									
_	on the sign.									
_										
2		of the offsite pond failed. It needs to be weeded, and stabelized with seed and mulch								
	per CGP 2.2.14.b									
3	Self inspection is required every 2 weeks until the final stabilization criteria (CGP 2.2.14.b) is									
	satisfied. Please provide the latest report.									
4 Silt fence is missing. Please construct silt fence as barrier to protect seed unless sta						ed unless stabilized				
	immediately with seed and gravel mulch.									
5			0							
5										
2.1	Discharge off site?	(Y/N)	no							
4	Self Inspec	tion Reports	requested	Latest rep	port Date:	6/15/2020				

Notes:			

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505) 924-3420 jhughes@cabq.gov

James D. Hughes